



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Cust No/Name	KCV05222/Mr Nor Hashim Bin Mohamad Isa
		Reg No/Reg Date	SMU1147P / 29/07/202
		Date In/Mileage	/ 15820
		Chassis No	MMBSTA13AKH003348
		Engine No	3A92UJB1536
		Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/11/2021/ 18:31	BLE	261 / Edwin Caina	17057

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & RR BUMPER BODY KIT <i>80</i>	<i>450 x 1.5 + 80</i>			<i>755</i> 1800.00
<i>1/2</i> REPAIR LHR FENDER & RR END PNL				
E PNT98000 RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL & LHR FENDER <i>350 x 3</i>				<i>1050</i> 1400.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET TO GIVE WAY FOR REPAIR				<i>120.00</i>
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				60.00
M SUNDRY Sundries				20.00
M UNPAINTED BODYKITS <i>x R</i>	1.00	1643.00	20.00	1314.40
M LAMP ASSY, COMB, RR LH <i>- OR</i>	1.00	337.00	23.00	259.49
M REFLECTOR LH <i>? x 11</i>	1.00	23.00	23.00	17.71
M FACE, RR BUMPER <i>- OR</i>	1.00	751.00	23.00	578.27
M BRACKET, RR BUMPER, LH <i>- OR</i>	1.00	28.00	23.00	21.56
M CLIP, FR BUMPER <i>- OR</i>	4	1.00	23.00	3.08
M MUD GUARD, RR LH <i>? x 11</i>	1.00	41.00	23.00	31.57

SURVEYOR NAME: Steve (LKK) 2/11/21, 10.00am
 SURVEYOR SIGNATURE: *OD- M M*
 DATE: _____
 REMARKS: *EXCISE - ?*
PIP
by Bal by
4 days

Confirm & accepted by <u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed	7% GST on	5,776.08	404.33
	Nett		5,776.08
	Total Payable		6,180.41

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.