



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21011172/Ktf3n2	
			Date: 21/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMV 943J	Veh. Inspected	FBG 3731T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103217/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA PCX	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	MLHJF28A1A5018813	Colour	BLACK	
Odometer	108774 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/90 R14	MICHELIN	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	100/90 R14	DUNLOP	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2021	Inspection Date	02/11/2021	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	