

# 萬汽車服務

## MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782

Website: <http://www.millionauto.com> Email: [wendy@millionauto.com](mailto:wendy@millionauto.com)

Tel: 6567 0817, 6264 9091 Fax: 6791 4716

Reg No: 317413/00-K GST Reg No: M90363176A

Vehicle No : GBG5234Z

Model : NISSAN NV200 1.5 MT

Chassis No : VSKYBAM20Z0146420

Year : 2017

### REPAIR ESTIMATE

S/N.	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (S) \$	Price (S) \$
1	FRONT BUMPER <i>de/</i>	1	\$ 275.00	\$ 275.00
2	FRONT BUMPER SIDE RETAINER <i>nu/</i>	2	\$ 22.00	\$ 44.00
3	FRONT BUMPER FOG LAMP <i>X nn</i>	2	\$ 175.00	\$ 350.00 <i>X</i>
4	FRONT BUMPER SIDE GARNISH <i>X nn</i>	2	\$ 225.00	\$ 450.00 <i>X</i>
5	FRONT BUMPER SPONGE <i>ca/</i>	1	\$ 125.00	\$ 125.00
6	FRONT BUMPER REINFORCEMENT <i>st/</i>	1	\$ 285.00	\$ 285.00
7	FRONT BUMPER UNDER COVER <i>ca/</i>	1	\$ 175.00	\$ 175.00
8	RADIATOR GRILLE <i>ca/</i>	1	\$ 170.00	\$ 170.00
9	RADIATOR GRILLE EMBLEM <i>ms/</i>	1	\$ 45.00	\$ 45.00
10	RADIATOR GRILLE LOWER MOULDING <i>sur/</i>	1	\$ 75.00	\$ 75.00
11	HEADLAMP ASSY <i>ca/</i>	2	\$ 225.00	\$ 450.00
12	HEADLAMP LOWER BRACKET <i>? XSUL</i>	2	\$ 45.00	\$ 90.00 <i>X</i>
13	HEADLAMP PANEL <i>? LH-bt/ RH-repair</i>	2	\$ 65.00	\$ 130.00 <i>65</i>
14	FRONT FENDER <i>X nn</i>	2	\$ 315.00	\$ 630.00 <i>X</i>
15	FRONT FENDER SIGNAL LAMP <i>X nn</i>	2	\$ 33.00	\$ 66.00 <i>X</i>
16	FRONT FENDER INNER SHIELD <i>X nn</i>	2	\$ 105.00	\$ 210.00 <i>X</i>
17	FRONT BONNET <i>bt/</i>	1	\$ 550.00	\$ 550.00
18	FRONT BONNET LOCK <i>st/</i>	1	\$ 45.00	\$ 45.00
19	FRONT BONNET HINGE <i>st/</i>	2	\$ 28.00	\$ 56.00
20	FRONT BONNET INSULATOR <i>X nn</i>	1	\$ 65.00	\$ 65.00 <i>X</i>
21	FRONT SUPPORT PANEL TOP <i>repair bt/</i>	1	\$ 300.00	\$ 300.00
22	FRONT SUPPORT PANEL SIDE <i>bt/ ? X nn</i>	2	\$ 40.00	\$ 80.00 <i>X</i>
23	AIR GUIDE LOWER <i>? ca/</i>	2	\$ 45.00	\$ 90.00
24	AIR GUIDE UPPER <i>? ca/</i>	2	\$ 40.00	\$ 80.00
25	AIRCON CONDENSER ASSY <i>st/</i>	1	\$ 400.00	\$ 400.00
26	AIRCON DISCHARGE HOSE <i>X nn</i>	1	\$ 210.00	\$ 210.00 <i>X</i>
27	AIRCON SUCTION PIPE <i>X nn</i>	1	\$ 200.00	\$ 200.00 <i>X</i>
28	RADIATOR ASSY <i>ca/</i>	1	\$ 350.00	\$ 350.00
29	RADIATOR TOP HOSE <i>X nn</i>	1	\$ 105.00	\$ 105.00 <i>X</i>
30	RADIATOR LOWER HOSE <i>X nn</i>	1	\$ 85.00	\$ 85.00 <i>X</i>
31	RADIATOR SPARE TANK <i>X nn</i>	1	\$ 55.00	\$ 55.00 <i>X</i>
32	TURBO INTERCOOLER <i>X nn</i>	1	\$ 680.00	\$ 680.00 <i>X</i>
33	TURBO AIR INLET HOSE <i>X nn</i>	1	\$ 95.00	\$ 95.00 <i>X</i>
34	FAN MOTOR ASSY <i>X nn</i>	1	\$ 300.00	\$ 300.00 <i>X</i>
35	HORN <i>X nn</i>	1	\$ 35.00	\$ 35.00 <i>X</i>
36	WIPER WASHER TANK <i>X nn</i>	1	\$ 185.00	\$ 185.00 <i>X</i>
37	AIR DUCT <i>X nn</i>	1	\$ 105.00	\$ 105.00 <i>X</i>

3580  
+ 106  
3938

\$	7,641.00
Plus 10%	\$ 764.10
Sub Total :	\$ 8,405.10

**PARTS REPLACEMENT - SPECIALNETT ITEMS**

1 FRONT NUMBER PLATE <i>CA</i>	\$	60.00	35
2 FRONT BUMPER CLIPS <i>CA</i>	\$	50.00	30
3 RADIATOR GRILLE CLIPS <i>CA</i>	\$	50.00	30
4 FRONT BONNET INSULATOR CLIPS <i>X 111</i>	\$	50.00	X
5 FRONT FENDER INNER SHIELD CLIPS <i>X 111</i>	\$	60.00	X
6 FRONT SUPPORT PANEL SEALANT <i>X 111</i>	\$	60.00	X
7 RADIATOR COOLANT <i>CA</i>	\$	50.00	40

135

Sub Total : \$ 380.00

**LABOUR AND MISCELLANEOUS CHARGES**

1 LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS	\$	1,600.00	700
2 TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	\$	1,500.00	500
3 TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	\$	100.00	40
4 TO CHECK WIRING AND LIGHTING FUNCTION	\$	80.00	30
5 TO REMOVE AND INSTALL AIR CON CONDENSER, FAN MOTOR, RADIATOR, TURBO INTERCOOLER AND TOP UP GAS	\$	200.00	100
6 TO PROGRAMMED DIAGNOSTIC CHECK	\$	150.00	80

1450

Sub Total : \$ 3,730.00

Grand Total : \$12,515.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasul  
Hp 90010068  
5 days  
H/S  
02/11/21 @ 1700hrs  
EXCESS : TBA  
REVERT  
Resurvey after repair

3938  
135  
1450  

---

5523  
20%  
4418.40  

---

H/S - \$4,400