

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782

Website: <http://www.millionauto.com> Email: wendy@millionauto.com

Tel: 6567 0817, 6264 9091 Fax: 6791 4716

Reg No: 317413/00-K GST Reg No: M90363176A

Vehicle No : GBG5234Z

Model : NISSAN NV200 1.5 MT

Chassis No : VSKYBAM20Z0146420

Year : 2017

REPAIR ESTIMATE

S/N.	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (S) \$	Price (S) \$
1	FRONT BUMPER <i>de /</i>	1	\$ 275.00	\$ 275.00
2	FRONT BUMPER SIDE RETAINER <i>na /</i>	2	\$ 22.00	\$ 44.00
3	FRONT BUMPER FOGLAMP <i>X</i>	2	\$ 175.00	\$ 350.00
4	FRONT BUMPER SIDE GARNISH <i>X</i>	2	\$ 225.00	\$ 450.00
5	FRONT BUMPER SPONGE <i>ca /</i>	1	\$ 125.00	\$ 125.00
6	FRONT BUMPER REINFORCEMENT <i>bt /</i>	1	\$ 285.00	\$ 285.00
7	FRONT BUMPER UNDER COVER <i>ca /</i>	1	\$ 175.00	\$ 175.00
8	RADIATOR GRILLE <i>ca /</i>	1	\$ 170.00	\$ 170.00
9	RADIATOR GRILLE EMBLEM <i>ms /</i>	1	\$ 45.00	\$ 45.00
10	RADIATOR GRILLE LOWER MOULDING <i>sure /</i>	1	\$ 75.00	\$ 75.00
11	HEADLAMP ASSY <i>ca /</i>	2	\$ 225.00	\$ 450.00
12	HEADLAMP LOWER BRACKET <i>?</i>	2	\$ 45.00	\$ 90.00
13	HEADLAMP PANEL <i>?</i>	2	\$ 65.00	\$ 130.00
14	FRONT FENDER <i>X</i>	2	\$ 315.00	\$ 630.00
15	FRONT FENDER SIGNAL LAMP <i>X</i>	2	\$ 33.00	\$ 66.00
16	FRONT FENDER INNER SHIELD <i>X</i>	2	\$ 105.00	\$ 210.00
17	FRONT BONNET <i>bt /</i>	1	\$ 550.00	\$ 550.00
18	FRONT BONNET LOCK <i>bt /</i>	1	\$ 45.00	\$ 45.00
19	FRONT BONNET HINGE <i>bt /</i>	2	\$ 28.00	\$ 56.00
20	FRONT BONNET INSULATOR <i>X repair</i>	1	\$ 65.00	\$ 65.00
21	FRONT SUPPORT PANEL TOP	1	\$ 300.00	\$ 300.00
22	FRONT SUPPORT PANEL SIDE <i>bt / ?</i>	2	\$ 40.00	\$ 80.00
23	AIR GUIDE LOWER <i>?</i>	2	\$ 45.00	\$ 90.00
24	AIR GUIDE UPPER <i>?</i>	2	\$ 40.00	\$ 80.00
25	AIRCON CONDENSER ASSY <i>bt /</i>	1	\$ 400.00	\$ 400.00
26	AIRCON DISCHARGE HOSE <i>X</i>	1	\$ 210.00	\$ 210.00
27	AIRCON SUCTION PIPE <i>X</i>	1	\$ 200.00	\$ 200.00
28	RADIATOR ASSY <i>?</i>	1	\$ 350.00	\$ 350.00
29	RADIATOR TOP HOSE <i>X</i>	1	\$ 105.00	\$ 105.00
30	RADIATOR LOWER HOSE <i>X</i>	1	\$ 85.00	\$ 85.00
31	RADIATOR SPARE TANK <i>X</i>	1	\$ 55.00	\$ 55.00
32	TURBO INTERCOOLER <i>X</i>	1	\$ 680.00	\$ 680.00
33	TURBO AIR INLET HOSE <i>X</i>	1	\$ 95.00	\$ 95.00
34	FAN MOTOR ASSY <i>X</i>	1	\$ 300.00	\$ 300.00
35	HORN <i>X</i>	1	\$ 35.00	\$ 35.00
36	WIPER WASHER TANK <i>X</i>	1	\$ 185.00	\$ 185.00
37	AIR DUCT <i>X</i>	1	\$ 105.00	\$ 105.00

\$ 7,641.00

Plus 10% \$ 764.10

Sub Total : \$ 8,405.10

PARTS REPLACEMENT -SPECIALNETT ITEMS

1	FRONT NUMBER PLATE	CM	\$	60.00	38
2	FRONT BUMPER CLIPS	new	\$	50.00	30
3	RADIATOR GRILLE CLIPS	new	\$	50.00	30
4	FRONT BONNET INSULATOR CLIPS	X	\$	50.00	X
5	FRONT FENDER INNER SHIELD CLIPS	X	\$	60.00	X
6	FRONT SUPPORT PANEL SEALANT	X	\$	60.00	X
7	RADIATOR COOLANT	new	\$	50.00	40

Sub Total : \$ 380.00

LABOUR AND MISCELLANEOUS CHARGES

1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS	\$	1,600.00	700
2	TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	\$	1,600.00	500
3	TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	\$	100.00	40
4	TO CHECK WIRING AND LIGHTING FUNCTION	\$	80.00	30
5	TO REMOVE AND INSTALL AIR CON CONDENDER, FAN MOTOR, RADIATOR, TURBO INTERCOOLER AND TOP UP GAS	\$	200.00	100
6	TO PROGRAMMED DIAGNOSTIC CHECK	\$	150.00	80

Sub Total : \$ 3,730.00

Grand Total : \$12,515.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
 Hp 90010068
 5 days
 L/S
 02/11/21 @ 1700hrs
 EXCESS: TBA
 REVERT
 Resurvey after repair