

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chenhor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJD 8867Z
TP/china

M/S: CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111
ATTN: Motor Claim Department

Claim No: ES2191054
Estimate No: ES2191054 /YISHUN
Date: 02 Nov 2021
Policy No: 5109381147-02
Veh Reg No: SJD8867Z
Make/Model: TOYOTA TOYOTA
COROLLA ALTIS 1.6L
CVT
Chassis No: MR053REH104509170
Engine No: 1ZRX417656
Reg. Date: 05/06/2014

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 01/11/2021
TP Veh Reg No: GBJ8381X

FAX: 62221033

Not Withheld
11 by @350d
Mummy After Pain
6 days

Estimate Repair Cost to Vehicle No : SJD8867Z

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Cost Plus				
1 REAR BUMPER	195.00	1 PC	195.00	✓
2 REAR BUMPER REINFORCEMENT	125.00	1 PC	125.00	✓
3 REAR BUMPER LH REFLECTOR	28.00	1 PC	28.00	✓
4 REAR BUMPER SIDE RETAINER	42.00	1 PC	42.00	✓
5 REAR BUMPER CLIPS	2.00	6 PCS	12.00	✓
6 REAR BOOT	350.00	1 PC	350.00	✓
7 REAR BOOT INNER LOCK	135.00	1 PC	135.00	✓
8 REAR BOOT INNER RUBBER	55.00	1 PC	55.00	✓
9 REAR BOOT LH REFLECTOR	50.00	1 PC	50.00	✓
10 REAR BOOT LOGO	32.00	1 PC	32.00	✓
11 REAR BOOT EMBLEM (COROLLA)	28.00	1 PC	28.00	✓
12 REAR BOOT EMBLEM (ALTIS)	28.00	1 PC	28.00	✓
13 REAR LH FENDER	380.00	1 PC	380.00	✓
14 REAR PANEL	210.00	1 PC	210.00	✓
15 TAILLAMP LH	0.00	1 PC	180.0000	✓
				1,850.00
Special Net				
16 REVERSE SENSOR	200.00	1 SET	200.00	✓
17 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
				240.00
Labour				
18 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
19 REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, GARNISH	100.00	1 LA	100.00	✓
20 RENEW REAR LH FENDER & REAR PANEL	1,100.00	1 LA	1,100.00	✓
21 PUTTY & RESPRAY ON REAR LH FENDER, REAR END PANEL, BOOT, REAR BOOT, REAR BUMPER	900.00	1 LA	900.00	✓
22 REMOVE & REFIX REVERSE CAMERA, SENSOR & RESET SYSTEM	30.00	1 LA	30.00	✓
23 RUSTPROOFING	60.00	1 LA	60.00	✓
				2,290.00

parts - 1562
bcs 20/ 312 40
1249 60
add SN 240 00
lab 2040 60
R 3079 60
1/1 3500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total SS 4,380.00
Add GST @ 7% 306.60
Total Amount payable SS 4,686.60

For Cheng Hoe Motor Pte Ltd