

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3589h ✓

27/10/21

MAKE REG: 13.10.2016

MODEL HYU- I40

Type

CHIANG/ NTUC

| Qty | Parts Description/ Labour | Unit Price | Amount |
|--|--|------------|-------------------|
| 1 | REAR BUMPER COVER | | \$553.00 |
| 10 | REAR BUMPER CLIPS | \$2.20 | \$22.00 |
| 1 | REAR BUMPER REINFORCEMENT <i>photo</i> | | \$428.40 |
| 1 | REAR BUMPER UNDER COVER | dislodged | \$228.00 |
| | SUB TOTAL | | \$1,231.40 |
| | 20.00% | | \$246.29 |
| | DISCOUNTED TOTAL | | \$985.17 |
| 1 | REAR REVERSE SENSOR | | \$135.70 |
| 1 | REAR BUMPER PROTECTOR | | \$50.00 |
| | | | \$172.13 |
| | Labour Charge | | |
| | Panel Beating | | \$420.00 |
| | Spray Painting Charge | | \$300.00 |
| | Remove/refix reverse sensor | | \$60.00 |
| | Check Lighting & Wiring | | \$40.00 |
| | TOTAL LABOUR | | \$820.00 |
| | ESTIMATE TOTAL | | \$1,977.30 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | |

Thuvan@Lkhauto.com
 2235769
 28/10/21 1600
 L/S after repair photo
 2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: