

AIG - OD CLAIM
SURVEY: 02/11/21
LKK - STEVE

VEHICLE NO : SLW 8474 A

MODEL : MIT/OUTLANDER 2.0 2WD CVT

WIP : 17070

Material	:	\$	<u>5,006.68</u>
Labour	:	\$	<u>2,015.00</u>
Sub-Total	:	\$	<u>7,021.68</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>6,421.68</u>
GST 7%	:	\$	<u>449.52</u>
Grand Total	:	\$	<u>6,871.20</u>
Finalise By/Date : <u>LARRY ON 18/11/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk.end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE


GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 02/11/2021	Cust No/Name	/Priyanka Ranade
	Reg No/Reg Date	SLW8474A / 05/03/2018
	Date In/Mileage	02/11/2021/ 34969
	Chassis/Package	GF7W0401155 /#GPP
	Engine No	4J11XM1892
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (992)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	18/11/2021/ 10:32	BLK	884 / Lauro Songcuan	17070		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE FRONT BUMPER, FRONT RH FENDER & AFFECTED AREAS					675.00 ✓
E PNT98000		SPRAY PAINT ON FRONT BUMPER, FRONT RH FENDER & FRONT RH DOOR					1050.00 ✓
E PNT88000		REMOVE & REPLACE BODY KIT					80.00 ✓
M SUNDRY		PERFORM RUST PREVENTION ON AFFECTED PORTIONS					40.00 ✓
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00 ✓
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00 ✓
M SUNDRY		SUNDRIES					20.00 ✓
X EXC		INSURANCE EXCESS					-600.00
X HEADLAMP ASSY,RH ✓			1.00	2135.00	23.00		1643.95 ✓
X FACE,FR BUMPER ✓			1.00	863.00	23.00		664.51 ✓
X BRACKET,FR BUMPER SIDE,RH ✓			1.00	18.00	23.00		13.86 ✓
X GARNISH,FR BUMPER,RH ✓			1.00	75.00	23.00		57.75 ✓
X BRKT,FR BUMPER SIDE,LWR RH ✓			1.00	6.00	23.00		4.62 ✓
X GARNISH,FR BUMPER SIDE ✓			1.00	112.00	23.00		86.24 ✓
X GARNISH,FR BUMPER SIDE ✓			1.00	220.00	23.00		169.40 ✓
X GARNISH,FR BUMPER SIDE ✓			1.00	48.00	23.00		36.96 ✓
X FENDER,FR RH ✓			1.00	622.00	23.00		478.94 ✓
X MOULDING,FR BUMPER,RH ✓			1.00	116.00	23.00		89.32 ✓
X MOULDING,FR WHEEL ARCH,RH ✓			1.00	199.00	23.00		153.23 ✓
X AERO KIT - OUTLANDER ✓			1.00	1554.00	00.00		1554.00 ✓
X RIVET,FR BUMPER			6.00	5.00	23.00		23.10
X CLIP,FR BUMPER			10.00	4.00	23.00		30.80
Z TEXT		AIG - OD CLAIM					
		DOA: 01/11/2021					

Supp

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLW 8474 A

<u>Materials</u>		<u>Cost \$</u>
1	Rivet, FR Bumper (6 pcs)	30.00 / <i>rec</i>
2	Clip, FR Bumper (10 pcs)	40.00 / <i>rec</i>
		70.00
23% Discount		16.10
		53.90
7% GST		3.77
		57.67

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SW 8474 AWIP: 17070 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	C/1P. FR BULK (X10)	? / SUPP			MR200300
2	RIVET. FR. BU (X6)	? / SUPP	<i>SW</i>		MRU001657
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: outlander 2.0SURVEYOR: Steve - MMR

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	DBA-GFTW XTX 2017MY

Ref No: 81W 8494A

Before use motor not to check all
is for sound

2021.11.11

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active	
KOS/IMMO/Keyless	KOS_8A880020	B1A11 U0184	Keyless/KOS key 2 low battery AUDIO CAN timeout	Active Active	
OSS	OSS_9588000B	U0184	AUDIO CAN timeout	Active	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error		

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2017MY

Page 844A

After we have not out to test
all the good
is done by the test drive

2021.11.11

All DTCS

2021.11.11

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
KOS/MMO/Keyless	KOS_8A880020	B1A11	Keyless/KOS key 2 low battery	Active	
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		