

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21011186/EVCN2**Date:** 12/11/2021**REFERENCE**

Insured/Claimant: GEORGE GOH CHEE CHONG (WU ZHICONG)
Date of Loss: 02/11/2021

Policy No: 1900131375

Nature of Claim: OD Claim No: 9223050517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN940J	Engine No:	G4FGKH739908
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MK5046047
Reg. Date:	25/07/2019 (Man. Year: 2018)	Odometer:	54711 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,349.00	2,486.40	1,862.60	42.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,300.00	750.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,399.00	3,786.40	2,612.60	40.83
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	6,099.00	3,486.40	2,612.60	42.84
+ GST 7.00/7.00% (S\$)	426.93	244.05	182.88	42.84
Nett Amount (S\$)	6,525.93	3,730.45	2,795.48	42.84

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
2	1		*GRILLE-FRONT BUMPER	Cut	262.00 F	*262.00 FL
3	1		*COVER-FR BUMPER FOG LAMP,LH	Not Necessary	15.00 F	*- FL
4	1		*LAMP ASSY-FRONT FOG,LH	Not Necessary	303.00 F	*- FL
5	1		*GRILLE ASSY-RADIATOR	Broken	328.00 F	*328.00 FL
6	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 F	*- FL
7	1		*MOULDING-FRONT BUMPER,LH	Not Necessary	36.00 F	*- FL
8	1		*LAMP ASSY-SIDE REPEATER,LH	Not Necessary	143.00 F	*- FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
10	1		*AIR-DUCT-FR BUMPER,LH	Not Necessary	14.00 F	*- FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 F	*- FL
12	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 F	*497.00 FL
13	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 F	*- FL
14	1		*LAMP ASSY-HEAD,LH	Cut	1,219.00 F	*1,219.00 FL
15	1		*ORNAMENT-KIA NO 115	Necessary	32.00 F	*32.00 FL
16	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
17	1		*GUARD-AIR,LH (Supplementary)	Crushed	28.00 F	*28.00 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	4,349.00 3,103.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 616.60
					Total Parts (\$\$)	4,349.00 2,486.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,FRT SUPPORT,REPAIR BONNET,FRT FENDER LH	New	800.00	400.00
2	SPRAY PAINT FOR FRT BUMPER,BONNET,FRT FENDER LH	New	1,050.00	700.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
Gross Labour Cost (\$)			2,050.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >