

Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Goh	Cust No/Name /Mr Goh
Blk 129A Canberra Street #04-644 Singapore 751129	Reg No/Reg Date SMN940J / 25/07/201
Contact No Mobile: 92327339	Date In/Mileage / 0
	Chassis No KNAF3416MK5046047
	Engine No G4FGKH739908
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	02/11/2021/ 10:05		442 / CocoLu	41954
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
E PNT88000 RENEW FRT BUMPER, FRT SUPPORT, REPAIR BONNET, FRT FENDER LH	400 X 1			400 / 800.00	
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER LH	350 X 2			700 / 1050.00	
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00	
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00	
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00	
M SUNDRY Sundry				20.00	
M COVER-FR BUMPER / BR	1.00	633.00	00.00	633.00	
M GRILLE-FRONT BUMPER / CUT A X AN	1.00	262.00	00.00	262.00	
M COVER-FR BUMPER FOG LAMP, LH	1.00	15.00	00.00	15.00	
M LAMP ASSY-FRONT FOG, LH	1.00	303.00	00.00	303.00	
M GRILLE ASSY-RADIATOR / BR	1.00	328.00	00.00	328.00	
M GARNISH-RADIATOR GRILLE	1.00	38.00	00.00	38.00	
M MOULDING-FRONT BUMPER, LH	1.00	36.00	00.00	36.00	
M LAMP ASSY-SIDE REPEATER, LH	1.00	143.00	00.00	143.00	
M ABSORBER-FRONT BUMPER ENERGY / BR (photo)	1.00	84.00	00.00	84.00	
M AIR DUCT-FR BUMPER, LH	1.00	14.00	00.00	14.00	
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	00.00	22.00	
M BEAM COMPLETE-FR BUMPER / BR (photo)	1.00	497.00	00.00	497.00	
M CARRIER ASSY-FRONT END MODULE	1.00	675.00	00.00	675.00	
M LAMP ASSY-HEAD, LH / CUT	1.00	1219.00	00.00	1219.00	
M ORNAMENT-KIA NO.115 / REC	1.00	32.00	00.00	32.00	

Steve (LKR)  
2/11/21, 10:30am

OR M-L  
Excess - ?  
P/P

Confirm & accepted by KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

My BL sy, 4 days

Nett 6,371.00  
7% GST on 6371.00 445.97  
Total Payable 6,816.97

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.