

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Mr Goh Blk 129A Canberra Street #04-644 Singapore 751129 Contact No Mobile: 92327339	Cust No/Name /Mr Goh Reg No/Reg Date SMN940J / 25/07/201 Date In/Mileage / 0 Chassis No KNAF3416MK5046047 Engine No G4FGKH739908 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	02/11/2021/ 10:05		442 / CocoLu	41954			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT8S000					400 X 1			800.00
RENEW FRT BUMPER, FRT SUPPORT , REPAIR BONNET, FRT FENDER LH								1050.00
E PNT98000					350 X 2			30.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER LH								120.00
A 90000001								50.00
CHECK WIRING & ELECTRICAL SYSTEM								20.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
FRT NUMBER PLATE WITH FRAME								
M SUNDRY								
Sundry					1.00	633.00	00.00	633.00
M COVER-FR BUMPER	BR				1.00	262.00	00.00	262.00
M GRILLE-FRONT BUMPER	CUT				1.00	15.00	00.00	15.00
M COVER-FR BUMPER FOG LAMP, LH					1.00	303.00	00.00	303.00
M LAMP ASSY-FRONT FOG, LH					1.00	328.00	00.00	328.00
M GRILLE ASSY-RADIATOR	BR				1.00	38.00	00.00	38.00
M GARNISH-RADIATOR GRILLE					1.00	36.00	00.00	36.00
M MOULDING-FRONT BUMPER, LH					1.00	143.00	00.00	143.00
M LAMP ASSY-SIDE REPEATER, LH					1.00	84.00	00.00	84.00
M ABSORBER-FRONT BUMPER ENERGY	BR (photo)				1.00	14.00	00.00	14.00
M AIR DUCT-FR BUMPER, LH					1.00	22.00	00.00	22.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	497.00	00.00	497.00
M BEAM COMPLETE-FR BUMPER	DO (photo)				1.00	675.00	00.00	675.00
M CARRIER ASSY-FRONT END MODULE					1.00	1219.00	00.00	1219.00
M LAMP ASSY-HEAD, LH	CUT				1.00	32.00	00.00	32.00
M ORNAMENT-KIA NO.115	APC							

Estimate

STERE (CLKK)

2/11/21, 10:30am

DO 1-1 AL

EXCEL - ?

P/P

Estimate

Steve CLKK
2/11/21, 10:30am

OR 1-1 AL
Excess - ?
P/P

My BL sy, 4 days

Nett 6,371.00
7% GST on 6371.00 445.97
Total Payable 6,816.97

Confirm & accepted by KK to Consultant hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items must be pre-approved and

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.