

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHD997SD

AAD2111-

*Not Withheld  
Re: B4paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD997SD

JTDKB3FU003091252

TOYOTA

PRIUS GEN 4

31/10/2021

III

03/08/2020

PART		LIST	
1	COVER, REAR BUMPER	\$ 485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ 332.70	X
1	GUARD, REAR BUMPER, CENTER	\$ DAM 374.50	✓
1	SEAL, REAR BUMPER SIDE, RH	\$ 118.30	X
1	RETAINER, REAR BUMPER SIDE, RH	\$ 132.60	X
1	REFLECTOR ASSY, REFLEX, RH	\$ 39.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$ 339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$ 261.00	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ 651.00	X

TOTAL \$ 2,734.30

25% \$ 683.58

\$ 2,050.73

**Special Nett**

1	REAR BUMPER SIDE CLIP	\$ 60.00	505a
1	TAIL LAMP CLIP	\$ 70.00	X
1SET	PARKING AID	\$ 700.00	X
1SET	REAR BUMPER CLIP	\$ 85.00	X
1	REAR BUMPER RETAINER CLIP	\$ 75.00	X
TOTAL		\$ 990.00	

TOTAL PARTS \$ 3,040.73

**LABOUR**

**Trans-cab Auto Services Pte Ltd****AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9978D**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *2000*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *2200*

To reinstall rear bumper parking sensor.

\$ 170.00 *500*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL** \$ **5,500.00****Over All Total** \$ **8,540.73****(PART-BY-PART) Repair Days***20 Days**1 1/2 day***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: