

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011189/AGA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0002793_02

Claimant Vehicle No : SNA5358P **Insured Vehicle No :** SLT8807P

Date of Loss: 01/11/2021 Nature of Claim: TP Claim No: MPC2021D0004754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA5358P**

Make & Model: VOLVO XC60, 2.0 T5 (A) Engine No: B4204T111077816

Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: YV1DZ40LDF2655572

Colour: Bronze Odometer: 101953 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,259.64	4,734.81	3,524.83	42.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	810.00	1,940.00	70.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,009.64	5,544.81	5,464.83	49.64
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	11,009.64	4,400.00	6,609.64	60.04
+ GST 7.00/7.00% (S\$)	770.67	308.00	462.67	60.03
Nett Amount (S\$)	11,780.31	4,708.00	7,072.31	60.04
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,195.45		
Global Sum Settlement (S\$)		5,150.00		

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021 Inspected At:

Estimated Period of Repair: 4.0 days

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki
Bukit
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2022)
Parts:	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA5358P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,360.40 FL	*1,645.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	133.90 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	572.50 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	270.80 FL	*- FL
5	1		*FRONT BUMPER LAMP RH	Not Necessary	248.30 FL	*- FL
6	1		*FRONT HEADLAMP RH	Cut	2,465.00 FL	*2,465.00 FL
7	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	93.40 FL	*- FL
8	1		*RH FRONT FENDER	Buckled	450.90 FL	*450.90 FL
9	1		*RH FRONT FENDER INNER SHIELD	Not Necessary	304.40 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
11	1		*LH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS
12	1		*LH FRONT SPORT RIM	Cut	1,450.00 FS	*600.00 FS
13	1		*LH FRONT TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,949.60	5,190.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	689.96	456.09
Total Parts (\$\$)	8,259.64	4,734.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	300.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	400.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY RUST PROOF /TUFF COATING ON ACCIDENT AREAS	New	300.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			2,750.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >