

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: LEE SOAK YEE
BLK 86 TELOK BLANGAH HEIGHTS
#29-379
SINGAPORE 100086

Estimate No: MC1902249
Date: 02 Nov 2021
Policy No: MP318650
Veh Reg No: SLA3854K
Make/Model: NISSAN NOTE 1.2 CVT
ABS D/AIRBAG 2WD
SDR

ATTN:

Not Authorized

Returning B4 pain

5 days

Your Ref No: -
Claim Type: Third Party
Accident Date: 31/10/2021
TP Veh Reg No: SKP996L

Estimate Repair Cost to Vehicle No :SLA3854K

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	498.00	✓
2 FRONT BUMPER	1 PC	570.00	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	29.60	✓
4 FRONT BUMPER CLIPS	12 PC	66.00	✓
5 FRONT FENDER RH	1 PC	554.00	✓
6 FRONT FENDER COWLING RH	1 PC	100.80	✓
7 FRONT FENDER COWLING CLIPS	8 PC	44.00	✓
8 FRONT FENDER BRACKET RH	1 PC	55.00	?
9 FRONT HOODLEDGE LOWER RH	1 PC	373.00	?
10 FRONT WHEEL HUB RH	1 PC	264.00	?
11 FRONT KNUCKLE ARM RH	1 PC	435.00	✓
12 FRONT LOWER ARM RH	1 PC	249.00	?
13 FRONT SHOCK ABSORBER RH	1 PC	373.00	?
14 FRONT SHOCK ABSORBER RH TOP MOUNTING	1 PC	108.20	?
15 FRONT STABILISER LINKAGE RH	1 PC	42.00	?
		3,761.60	
	Less 10%	376.16	3,385.44
16 FRONT WHEEL BEARING RH	1 PC	134.60	✓
		134.60	134.60
Special Nett			
17 SPORT RIM	1 PC	708.00	✓
		708.00	
	0%	70.80	637.20
18 TYRE -CHECK PRICE	1 PC	0.0000	?
		0.00	0.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
20 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
21 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.(RHF)	1 PC	180.00	1601
22 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT WHEEL PANEL RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	4001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LEE SOAK YEE
BLK 86 TELOK BLANGAH HEIGHTS
#29-379
SINGAPORE 100086

ATTN:

Estimate No: MC1902249
Date: 02 Nov 2021
Policy No: MP318650
Veh Reg No: SLA3854K
Make/Model: NISSAN NOTE 1.2 CVT
ABS D/AIRBAG 2WD
SDR

Your Ref No: -
Claim Type: Third Party
Accident Date: 31/10/2021
TP Veh Reg No: SKP996L

Estimate Repair Cost to Vehicle No :SLA3854K

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23 TO SPRAY FRONT BUMPER, FRONT FENDER RH, FRONT WHEELHOUSE PANEL RH	1 PC	600.00	600.00
		1,400.00	1,400.00
		Total	S\$ 5,557.24
		Add GST @ 7%	389.01
		Total Amount Payable	S\$ 5,946.25

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED FORTY SIX AND CENTS TWENTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE