

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowok@gmail.com



DATE : 01.11.2021

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLH1261Y**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 30.10.2021
TIME OF ACCIDENT : 10:30HRS

RV31000687

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER (UPPER) <i>Distold</i>	1	\$ 927.50	\$ 927.50
2	FRONT BUMPER (LOWER) <i>lt</i>	1	\$ 439.10	\$ 439.10
3	FRONT BUMPER LOWER DIFFUSER <i>lt</i>	1	\$ 381.70	\$ 381.70
4	FRON BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 532.60	\$ 532.60
5	FRONT BUMPER SENSOR <i>1 piece dnd</i>	4	\$ 126.70	\$ 506.80
6	FRONT BUMPER SENSOR HOLDER <i>2 pieces</i>	4	\$ 25.30	\$ 101.20
7	FRONT BUMPER FOGLAMP <i>cut LH</i>	2	\$ 510.70	\$ 1,021.40
8	FRONT BUMPER FOGLAMP COVER <i>cut LH</i>	2	\$ 60.20	\$ 120.40
9	FRONT BUMPER LOWER GRILLE <i>Delnd</i>	1	\$ 150.20	\$ 150.20
10	FRONT BUMPER SIDE RETAINER <i>LH cnd</i>	2	\$ 23.00	\$ 46.00
11	FRONT BUMPER REINFORCEMENT TOP GARNISH <i>new</i>	2	\$ 95.00	\$ 190.00
12	FRONT BUMPER REINFORCEMENT <i>Delnd</i>	1	\$ 386.90	\$ 386.90
13	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 65.30	\$ 65.30
14	FRONT FENDER <i>Distold LH, RH Rpt</i>	2	\$ 580.00	\$ 1,160.00
15	FRONT FENDER COWLING <i>new</i>	2	\$ 146.00	\$ 292.00
16	FRONT FENDER ARCD GARNISH <i>Delnd</i>	2	\$ 195.80	\$ 391.60
17	FRONT WHEEL HOUSE SUPPORT PANEL LH <i>Rpt</i>	1	\$ 263.00	\$ 263.00
18	FRONT WHEEL HOUSE EXTEND PANEL LH <i>Rpt</i>	1	\$ 163.00	\$ 163.00
19	CENTER GRILLE TOP COVER <i>Delnd</i>	1	\$ 169.00	\$ 169.00
20	CENTER GRILLE LOGO <i>new</i>	1	\$ 39.00	\$ 39.00
21	CENTRE GRILLE BASE <i>cnd</i>	1	\$ 463.00	\$ 463.00
22	CENTER GRILLE OUTER MOULDING <i>cnd</i>	1	\$ 368.00	\$ 368.00
23	CENTER GRILLE UPPER MOULDING <i>new</i>	1	\$ 84.00	\$ 84.00
24	CENTER GRILLE LOWER MOULDING <i>cnd</i>	2	\$ 84.00	\$ 168.00
25	CENTER GRILLE CHROME MOULDING <i>cnd</i>	1	\$ 138.00	\$ 138.00

✓
✓
✓
✓
126.70
50.60
510.70
60.20
—
23.
+
—
+
880.
+
+
✓
✓
✓
✓
+
✓
✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLH1261Y**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 30.10.2021
 TIME OF ACCIDENT : 10:30HRS

26	CENTRE GRILLE SUPPORT BRACKET <i>Neu</i>	1	\$ 217.00	\$ 217.00	+
27	HEADLAMP (LED) <i>LH cracked</i>	2	\$ 3,679.00	\$ 7,358.00	3679. 3200
28	HEADLAMP LOWER BRACKET <i>LH cracked</i>	2	\$ 67.00	\$ 134.00	67.
29	BONNET <i>Distorted</i>	1	\$ 1,326.00	\$ 1,326.00	1180
30	BONNET LOCK <i>Neu</i>	1	\$ 178.00	\$ 178.00	+
31	BONNET INNER RUBBER (FRONT) <i>3AP</i>	2	\$ 27.00	\$ 54.00	+
32	BONNET INNER RUBBER (SIDE) <i>Neu</i>	2	\$ 29.00	\$ 58.00	+
33	BONNET INSULATOR <i>cracked</i>	1	\$ 274.00	\$ 274.00	✓
34	BONNET STOPPER <i>Not Nec.</i>	2	\$ 19.50	\$ 39.00	+
35	BONNET HINGE <i>LH Bent</i>	2	\$ 45.00	\$ 90.00	45
36	FRONT SUPPORT PANEL <i>Repa Distorted</i>	1	\$ 796.00	\$ 796.00	+
37	FRONT SUPPORT PANEL TOP GARNISH <i>Neu</i>	1	\$ 185.00	\$ 185.00	+
38	RADIATOR <i>Distorted</i>	1	\$ 1,365.00	\$ 1,365.00	✓
39	RADIATOR SIDE GARNISH <i>LH cracked</i>	2	\$ 68.00	\$ 136.00	68
40	RADIATOR RUBBER MOUNTING <i>Neu</i>	4	\$ 28.00	\$ 112.00	+
41	RADIATOR FAN COWLING <i>cracked</i>	1	\$ 175.00	\$ 175.00	+
42	RADIATOR BRACKET <i>Neu</i>	2	\$ 64.00	\$ 128.00	+
43	AIR CON CONDENSER <i>Bent</i>	1	\$ 1,160.00	\$ 1,160.00	✓
44	AIR CON CONDENSER MOUNTING RUBBER <i>Neu</i>	4	\$ 28.00	\$ 112.00	+
45	AIR CON FAN COWLING <i>3AP</i>	1	\$ 168.00	\$ 168.00	+
46	AIR CON CONDENSER BRACKET	2	\$ 35.00	\$ 70.00	+
47	AIR DUCT <i>Neu</i>	1	\$ 142.00	\$ 142.00	+
48	AIR FLEXIBLE DUCT <i>Neu</i>	1	\$ 165.00	\$ 165.00	+
49	AIR CLEANER RESONATOR BOX <i>cracked</i>	1	\$ 387.00	\$ 387.00	✓
50	AIR CLEANER RESONATOR DUCT <i>Neu</i>	1	\$ 139.00	\$ 139.00	+
51	FRONT TEMPERATURE SENSOR <i>Neu</i>	1	\$ 142.00	\$ 142.00	+
52	HORN <i>Neu</i>	1	\$ 105.00	\$ 105.00	+
53	BATTERY TRAY	1	\$ 38.00	\$ 38.00	+
54	BATTERY BRACKET <i>3AP</i>	1	\$ 68.00	\$ 68.00	+
55	BATTERY BASE PANEL <i>Neu</i>	1	\$ 87.00	\$ 87.00	+
56	FRONT FUSE BOX LH <i>Neu</i>	1	\$ 865.00	\$ 865.00	+
57	FRONT TEMPERATURE SENSOR <i>Neu</i>	1	\$ 142.00	\$ 142.00	+

*Relay Box 285 ✓
 cracked*

TOTAL PRICE \$ 24,982.70
 LESS 20% \$ 4,996.54
 SUB TOTAL PRICE \$ 19,986.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Distorted</i>	1	\$ 50.00	\$ 50.00

Handwritten notes and marks on the right side of the page, including checkmarks, plus signs, and numerical values like 3200, 1180, 67, 45, 68, 14907.80, and 11926.24.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLH1261Y**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 30.10.2021
 TIME OF ACCIDENT : 10:30HRS

2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	FRONT FENDER ARCD GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
5	CENTRE GRILLE CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
6	ENGINE UNDER CENTER COVER CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
7	BONNET SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
8	BONNET INSULATOR CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
9	FRONT WHEEL HOUSE SUPPORT PANEL SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
10	FRONT SUPPORT PANEL SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
11	FRONT SUPPORT PANEL TOP GARNISH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
12	RADIATOR SIDE GARNISH LH (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
13	FRONT FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
14	FRONT FENDER ARCED GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
15	COOLANT <i>New</i>	1	\$ 40.00	\$ 40.00	<i>230</i>

TOTAL \$ 750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>1200</i>
3	REMOVE AND REFIX WIREHARNES AND WIRING CHECKING	\$ 180.00	<i>120</i>
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>X</i>
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>X</i>

TOTAL \$ 4,100.00

TOTAL PARTS COST : \$ 20,736.16
 TOTAL LABOUR COST : \$ 4,100.00

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLH1261Y**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 30.10.2021
TIME OF ACCIDENT : 10:30HRS

TOTAL REPAIR COST : \$ 24,836.16

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian King,
L/S 02/11/21.

08 Days.

total: 14646.24

L/S: 11.7K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: