

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM THIAM LENG
 25 TAMPINES ST 86 #02-18
 SINGAPORE 528569

Contact : 81391917

T? AXA
 Asher.

TAX INVOICE

Repair Code : CLM16974
 Date in : 01/11/2021
 Vehicle Num. : SLM7401U
 Model : HONDA VEZEL 1.5X CVT
 Chassis/Eng# : RU11210662/L15B4410664

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	463.70	✓ 463.70
REAR BUMPER LOWER COVER <i>Del d.</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>Conced</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>Del d</i>	2	195.00	✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Distorted</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR <i>conced</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>Del d</i>	1	98.00	✓ 98.00
REAR FENDER ARCH GARNISH L/R <i>new</i>	2	195.00	+ 390.00
REAR FENDER INNER TRIM GARNISH L/R <i>new</i>	2	295.00	+ 590.00
REAR FLOOR PANEL COMPARTMENT SPONGE TRAY <i>conced</i>	1	485.30	✓ 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Del d</i>	1	430.30	✓ 430.30 <i>285</i>
REAR TAILGATE <i>Del d</i>	1	953.30	✓ 953.30
REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	✓ 56.20
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	+ 100.00
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	153.40	+ 153.40
REAR TAILGATE INNER TRIM GARNISH <i>conced</i>	1	180.00	✓ 180.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM THIAM LENG
 25 TAMPINES ST 86 #02-18
 SINGAPORE 528569

Contact : 81391917

TAX INVOICE

Repair Code : CLM16974
 Date in : 01/11/2021
 Vehicle Num. : SLM7401U
 Model : HONDA VEZEL 1.5X CVT
 Chassis/Eng# : RU11210662/L15B4410664

REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	<i>4467-30</i>	1	180.00	<input checked="" type="checkbox"/>	180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>new</i>	<i>3573-84</i>	1	27.50	<input type="checkbox"/>	27.50
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	<i>1757-30</i>	2	18.50	<input type="checkbox"/>	37.00
REAR TAILGATE WEATHER STRIP <i>ut</i>	<i>3429-84</i>	1	96.80	<input checked="" type="checkbox"/>	96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>new</i>		2	50.00	<input checked="" type="checkbox"/>	100.00
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>		2	50.00	<input checked="" type="checkbox"/>	100.00

Subtotal before discount 5,970.60

Percentage discount 20% 1,194.12

Sub-total 1 4,776.48

REAR BUMPER CLIPS - SET <i>new</i>		1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>		1	280.00	<i>2w</i>	280.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>		2	30.00	<input type="checkbox"/>	60.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>		1	60.00	<input type="checkbox"/>	60.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>		1	40.00	<input type="checkbox"/>	40.00
REAR TAILGATE SPOILER CLIPS - SET <i>new</i>	<i>290</i>	1	50.00	<input type="checkbox"/>	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>		1	60.00	<input checked="" type="checkbox"/>	60.00

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM THIAM LENG
 25 TAMPINES ST 86 #02-18
 SINGAPORE 528569

Contact : 81391917

TAX INVOICE

Repair Code : CLM16974
 Date in : 01/11/2021
 Vehicle Num. : SLM7401U
 Model : HONDA VEZEL 1.5X CVT
 Chassis/Eng# : RU11210662/L15B4410664

Subtotal before discount	600.00
Percentage discount 0%	0.00
Sub-total 2	600.00
Parts-total	5,376.48

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	50 80.00
To remove, reinstall tailgate windscreen	120. 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60. 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800. 1000.00
To apply anti-rust chemical on repaired and replaced panel.	60 100.00
To remove n refix rear gate mechanism and check for function	60 80.00
Labour Total	2,510.00
Parts & Labour Total	7,886.48

*** This is a computer-generated document which requires no signature.***

Adnan Lij
 02/11/21 Y/S
 06 days
 total: 5813.84
 A/S: 4.6k
 total: 5813.84
 A/S: 4.6k