



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

02/11/2021

01-43

Singapore 417883

Accident date : 01/11/2021

Estimated repair cost for vehicle no : SJK9736A MITSUBISHI LANCER 1.5 MIVEC GLS

CHASSIS: JMYSRCY2A9U001782 (2008)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Distorted</i>	\$815.60	\$815.60 ✓
2	1	REAR BUMPER REINFORCEMENT <i>Best</i>	\$458.40	\$458.40 254 ✓
3	2	REAR BUMPER SIDE RETAINER <i>Best</i>	\$96.10	\$192.20 90 ✓
4	1	REAR BUMPER CENTER BEAM <i>Best</i>	\$198.20	\$198.20 ✓
5	2	REAR BUMPER REFLECTOR <i>cut</i>	\$95.60	\$191.20 ✓
6	1	REAR BUMPER TOW COVER <i>cut</i>	\$55.60	\$55.60 ✓
7	2	REAR BUMPER NUMBER PLATE LAMP <i>cut</i>	\$99.30	\$198.60 ✓
8	2	REAR BUMPER NUMBER PLATE LAMP BRACKET <i>Best</i>	\$43.60	\$87.20 ✓
9	1	REAR BUMPER NUMBER PLATE WIRE HARNESS <i>new</i>	\$321.20	\$321.20 + ✓
10	1	REAR BOOTLID <i>Buckled</i>	\$693.10	\$693.10 ✓
11	1	REAR BOOTLID LOCK <i>new</i>	\$298.60	\$298.60 155 ✓
12	1	REAR BOOTLID LOCK CATCH <i>new</i>	\$143.60	\$143.60 + ✓
13	1	REAR BOOTLID LOCK DETECTOR <i>cut</i>	\$165.40	\$165.40 ✓
14	1	REAR BOOTLID INNER TRIM BOARD <i>new</i>	\$298.70	\$298.70 + ✓
15	2	REAR BOOTLID HINGE <i>new</i>	\$98.10	\$196.20 + ✓
16	2	REAR BOOTLID SHOCK ABSORBER <i>new</i>	\$328.40	\$656.80 + ✓
17	2	REAR BOOTLID LAMP <i>cut</i>	\$389.40	\$778.80 642 ✓
18	1	REAR BOOTLID EMBLEM LOGO <i>new</i>	\$55.60	\$55.60 ✓
19	1	REAR BOOTLID THIRD BRAKE LAMP <i>new</i>	\$165.30	\$165.30 + ✓
20	1	REAR WEATHER STRIPE <i>cut</i>	\$214.50	\$214.50 ✓
21	1	REAR END PANEL <i>Dented</i>	\$589.10	\$589.10 ✓
22	1	REAR END PANEL TOP GARNISH <i>Delord</i>	\$235.60	\$235.60 144 ✓
23	2	REAR FENDER INNER TRIM <i>torn</i>	\$497.60	\$995.20 446 ✓
24	1	REAR SPARE TYRE COMPARTMENT PANEL <i>new</i>	\$954.30	\$954.30 + ✓
25	1	REAR SPARE TYRE TOP BOARD <i>torn</i>	\$447.30	\$447.30 158 ✓
26	1	REAR EXHUAUST MUFFLER <i>new</i>	\$983.60	\$983.60 + ✓
27	1	REAR EXHUAUST MUFFLER SHIELD <i>new</i>	\$124.60	\$124.60 + ✓
28	2	REAR EXHUAUST MUFFLER RUBBER MOUNTING <i>new</i>	\$42.30	\$84.60 + ✓
29	2	REAR TAILLAMP <i>cut</i>	\$489.20	\$978.40 712 ✓

30	2	REAR TAILLAMP LOWER BRACKET <i>Not in</i>	\$86.40	\$172.80 +
31	1	REAR KEYLESS SENSOR <i>3 Repeated</i>	\$288.40	\$288.40 +
32	1	REAR KEYLESS BUZZER	\$213.20	\$213.20 +

5865.10
5278.59

TOTAL :	\$12,251.90
LESS 10 %	\$1,225.19
SUB-TOTAL :	\$11,026.71

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	2	REAR TAILLAMP CLIPS <i>new</i>	\$12.00	\$24.00 ✓
3	1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$60.00	\$60.00 <i>10</i>
4	1	REAR END PANEL SEALANT <i>new</i>	\$80.00	\$80.00 <i>60</i>
5	1	REAR NUMBER PLATE WITH CASING <i>Dented</i>	\$60.00	\$60.00 <i>50</i>
6	1	REAR BUMPER REVERSE SENSOR <i>Damaged</i>	\$250.00	\$250.00 <i>20</i>

374

TOTAL:	\$554.00
TOTAL PARTS :	\$11,580.71

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING
- 5 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 6 LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHUAUST PIPE

\$1,800.00 *1000*
\$1,400.00 *1000*
\$80.00 *30*
\$200.00 *80*
\$300.00 *60*
\$250.00 +

7 Labour to remove reverse sensor

100 50.

Subtotal :- \$3,780.00

Total:- \$15,360.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lij
L/S 02/11/21
06 Days

total: 7872.59
L/S: 6.3K

6.3K