



Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD52265

Not Authored
Recovery B4 paint

AAD2110-

82072-43

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD52265

JTDKB3FU103078395

TOYOTA

PRIUS

27/10/2021

EQ

12/12/2018

01 NOV 2021

PART	
1 HOOD SUB-ASSY	
1 HINGE ASSY, HOOD, LH	
1 HINGE ASSY, HOOD, RH	
1 LOCK ASSY, HOOD	
1 COVER, FRONT BUMPER	
1 ABSORBER, FRONT BUMPER ENERGY	
1 UNIT ASSY, HEADLAMP, LH	
1 UNIT ASSY, HEADLAMP, RH	
1 GRILLE SUB-ASSY, RADIATOR	
1 EMBLEM ASSY, RADIATOR GRILLE	
1 GRILLE, RADIATOR, LOWER NO.1	

LIST

\$	983.10	✓
\$	58.90	X
\$	58.90	X
\$	135.00	✓
\$	516.00	✓
\$	79.60	X
\$	2,637.60	X
\$	2,637.60	X
\$	346.00	X
\$	90.80	✓
\$	170.10	X

TOTAL	\$	7,713.60
25%	\$	2,828.00
	\$	8,484.00

Special Nett

1SET FRONT BUMPER CLIP	
1 FRT NUMBER PLATE WITH MOULDING	
1 FRT BUMPER SIDE RETAINER CLIP	

\$	90.00	505N-
\$	200.00	455N-
\$	75.00	X

TOTAL	\$	365.00
-------	----	--------

TOTAL PARTS	\$	9,530.50
-------------	----	----------

LABOUR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5226S

AAD2110-

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	300%
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30%
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	440%
To Check Electrical Lighting Concerned.	\$	170.00	15%

TOTAL \$ 5,610.00

Over All Total \$ 14,459.00

(PART-BY-PART) Repair Days

~~20~~ days

2 1/2 days