

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI21011197/Evf3e2	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Date:	23/12/2021	
			Code:	FCI2	
1.		Policy Particulars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	XE 2870G	
	Policy No.	D-21097702MFVS/6	Coverage (\$)	0.00	
	Claim No.	D21003069MFVS	Excess (\$)	3,000.00	
	Assign From	ESTHER LIM	Assign Date	02/11/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	UD TRUCKS CWB5ELPHNT	c.c	10837	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JNCM1F1D7HU019260	Colour	WHITE	
	Odometer	134654 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
			DDIDOCCTONE	4 mm	
	R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
	R/H Rear Tyre L/H Rear Tyre	295/80 R22.5 295/80 R22.5	BRIDGESTONE	4 mm	
4.	.	295/80 R22.5			
4.	L/H Rear Tyre	295/80 R22.5	BRIDGESTONE on of Damages		
4.	L/H Rear Tyre	295/80 R22.5 Description STAINED DAMAGES AT THE FROM	BRIDGESTONE on of Damages		
4.	L/H Rear Tyre THE VEHICLE SUS	295/80 R22.5 Description STAINED DAMAGES AT THE FROM ETAILS.	BRIDGESTONE on of Damages		
	L/H Rear Tyre THE VEHICLE SUS	295/80 R22.5 Description STAINED DAMAGES AT THE FROM ETAILS.	BRIDGESTONE on of Damages ONT N/S PORTION.		
	L/H Rear Tyre THE VEHICLE SUSTINATION DAMAGES SEE D	295/80 R22.5 Description STAINED DAMAGES AT THE FROM ETAILS. General	BRIDGESTONE on of Damages ONT N/S PORTION. Information Inspection Date	4 mm	
	THE VEHICLE SUSTANDAMAGES SEE D	295/80 R22.5 Description STAINED DAMAGES AT THE FROM ETAILS. General 25/10/2021	BRIDGESTONE On of Damages ONT N/S PORTION. Information Inspection Date SERVICE PTE LTD	4 mm 03/11/2021	
	THE VEHICLE SUSTANDAMAGES SEE D	Description STAINED DAMAGES AT THE FROM ETAILS. General 25/10/2021 SNG AH TEE MOTOR & PANEL BLK 3, PIONEER ROAD NORTH	BRIDGESTONE On of Damages ONT N/S PORTION. Information Inspection Date SERVICE PTE LTD	4 mm 03/11/2021	
5.	L/H Rear Tyre THE VEHICLE SUSTINE DAMAGES SEE DI Accident Date Survey held at A)DAMAGES CON B)THE MARKET V	Description STAINED DAMAGES AT THE FROM ETAILS. General 25/10/2021 SNG AH TEE MOTOR & PANEL BLK 3, PIONEER ROAD NORTH RESISTENT TO ACCIDENT REPOR ALUE IS \$\$100,000.00(EST. AVE	BRIDGESTONE On of Damages ONT N/S PORTION. Information Inspection Date SERVICE PTE LTD H, #01-18 SINGAPORE 628 Emarks T. RAGE)	4 mm 03/11/2021 3457.	
5.	L/H Rear Tyre THE VEHICLE SUSTINE DAMAGES SEE DI Accident Date Survey held at A)DAMAGES CON B)THE MARKET V	Description STAINED DAMAGES AT THE FROM ETAILS. General 25/10/2021 SNG AH TEE MOTOR & PANEL BLK 3, PIONEER ROAD NORTH Re ESISTENT TO ACCIDENT REPOR ALUE IS \$\$100,000.00(EST. AVE DE TO YOUR INSTRUCTIONS, W	BRIDGESTONE On of Damages ONT N/S PORTION. Information Inspection Date SERVICE PTE LTD H, #01-18 SINGAPORE 628 Emarks T. RAGE)	4 mm 03/11/2021 3457.	
5. 5a.	L/H Rear Tyre THE VEHICLE SUSTINE DAMAGES SEE DITEMPTED Accident Date Survey held at A)DAMAGES CONB)THE MARKET VC)IN ACCORDANCE	Description STAINED DAMAGES AT THE FROM ETAILS. General 25/10/2021 SNG AH TEE MOTOR & PANEL BLK 3, PIONEER ROAD NORTH Re ESISTENT TO ACCIDENT REPOR ALUE IS \$\$100,000.00(EST. AVE DE TO YOUR INSTRUCTIONS, W	BRIDGESTONE on of Damages ONT N/S PORTION. Information Inspection Date SERVICE PTE LTD H, #01-18 SINGAPORE 628 Emarks T. RAGE) E HAVE AUTHORISED RE Days of Repair	4 mm 03/11/2021 3457.	