



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21011200/Btf3n2	Date: 19/11/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 527C	Veh. Inspected	GBK 4724L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10012272/HA	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	02/11/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE TURBO	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTFHT02P509990022	Colour	SILVER	
Odometer	49851 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/10/2021	Inspection Date	03/11/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	