

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: GBK4724L
 Make and model: Toyota Hiace
 Chassis: JTFHT02P509990022

2020

Qty Spare partsList price

1	Bonnet	\$	845.00	NDX
1	Bonnet emblem	\$	75.00	NNX
1	Bonnet lock	\$	94.00	NDX
1	Front bumper	\$	496.00	BRV ✓
1	Front bumper LH side garnish	\$	89.00	NDX
1	Front bumper lower grille	\$	✓ 218.00	BRV
1	Front bumper centre beam	\$	274.00	} NDX
1	Front bumper reinforcement	\$	348.00	
1	Front bumper RH side retainer	\$	130.00	151.00
1	Front bumper LH side retainer	\$	130.00	151.00
1	Front grille base	\$	450.00	503.00
1	Front grille upper garnish	\$		213.00
1	Front grille lower garnish	\$		✓ 351.00
1	RH headlamp assy	\$		✓ 902.00
1	RH headlamp lock holder	\$		26.00
1	LH headlamp assy	\$		✓ 902.00
1	LH headlamp lock holder	\$		26.00
1	Washer tank	\$		166.00
1	Aircon condenser	\$		1,968.00
1	Radiator assy	\$		2,375.00
1	Support panel	\$		388.00

\$ 3579.00 10,561.00
 -25% \$ 894.75 2,640.25
 \$ 2684.25 7,920.75

Qty Spare partsSpecial Nett price

1	Front number plate	\$	30.00	70.00	BT ✓
1set	Front bumper clips	\$	30.00	70.00	NECV ✓
1	Radiator coolant	\$		60.00	NNX
1set	Front grille clips	\$	30.00	60.00	NECV ✓

90.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 400.00 1,000.00 ✓

Spray painting on affected panels

\$ 300.00 1,000.00 ✓

Check wiring and lighting system

\$ 80.00 NNX

Apply rust coating chemical on affected panels

\$ 50.00

Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas

\$ 220.00

Remove and replace radiator assy, pipes and fan assy to assist repair. To refill coolant

\$ 220.00

Refocus and adjust headlamps assy

\$ 50.00

700.00

Total: \$ 10,800.75

Survey & Resurvey Not
3/11/2021 necessary, all external damages only

1450 hrs

TG Lim Mui

Lump sum repair

Repair days 4

Parts 2684.25

SN 90.00

Labour 700.00

3474.25

@ 20% 694.85

2779.40

LS 2750/2

TG Lim Mui

4/11/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: