

TPAIG.

Justin.

SFE 628S 2013 Dec

Mercedes Benz E250 1991cc

WDD2120362A819710

Rear Bumper Deband

1728.

Rear Bumper Clips. New

50(SN)

Rear Bumper Side Holder x 02

74 x 2 = 148

Rear Bumper Lower Garnish. Cut

369

Rear Bumper Reinforcement.

765

Rear Bumper Tow Cover

67

Rear Bumper Side Chrome Trim x 02

137 x 2 = 274

Reverse Sensor x 04. 2 pieces each

260 x 4 = 1040

Taillamp x 02

685 x 2 = 1370

Panel Beating

~~500~~ 200

Spray Painting.

~~600~~ 250

Wiring

~~50~~ 30

To remove reverse sensor

~~100~~ 50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

list: 2891

less 10%: 2601.90

S.N.: 50

Labour: 530

total: 3181.90

L/S: 25K.

02 Days.