



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201344

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/03/2022
Reference CC6/CTI21011203/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLW 3842D
Insured Veh. SMY 1631L
Claim No. SNM21D206186/C02
Policy No. DMPCSNW00132342100
Accident Date 19/10/2021
Inspection Date 01/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21011203/Aea3q2	
			Date: 14/03/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 1631L	Veh. Inspected	SLW 3842D	
Policy No.	DMPCSNW00132342100	Coverage (\$)	0.00	
Claim No.	SNM21D206186/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZVW400027018	Colour	BLUE	
Odometer	336013 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	FIRENZA	6 mm	
L/H Front Tyre	205/60 R16	FIRENZA	6 mm	
R/H Rear Tyre	205/60 R16	FIRENZA	6 mm	
L/H Rear Tyre	205/60 R16	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2021	Inspection Date	01/11/2021	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 3842D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	556.40	556.40
1	FRONT BUMPER LOWER	DEFORMED	580.10	334.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	278.90	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	691.50	-
1	FRONT GRILLE	CRACKED	422.90	422.90
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	230.10	-
2	FRONT HEADLAMP @\$959.20	O/S CRACKED	1,918.40	959.20
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,127.90	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	301.90	-
1	BONNET	NOT NECESSARY	938.10	-
1	FRONT LOGO	NECESSARY	189.40	89.00
1	FRONT BUMPER SPONGE	CRACKED	187.00	187.00
1	FRONT BUMPER INNER COVER	DEFORMED	245.00	245.00
	LESS 25% DISCOUNT		-1,916.90	-698.38
			5,750.70	2,095.12
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT NUMBER PLATE WITH CASING (SN)	BENT	60.00	60.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	120.00	-
			320.00	90.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING.		1,400.00	400.00
	LABOUR FOR SPRAYPAINTING.		1,000.00	250.00
	LABOUR FOR REMOVE & REFIX AIR CON CONDENSER ,TOP UP AIR CON GAS.	NOT NECESSARY	150.00	-
	LABOUR FOR REMOVE & REFIX RADIATOR ,TOP UP RADIATOR COOLANT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS.	NOT NECESSARY	200.00	-
			2,980.00	680.00
GRAND TOTAL			9,050.70	2,865.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC6/CTI21011203/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 3842D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 3842D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

