



TRANS EUROKARS PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042

EUROKARS SERVICES

ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L		NAME :		WIP : 43037	
64 CECIL STREET		ADDRESS :		EXCESS :	
#04-#05 IOB BUILDING				DATE: 27-Oct-21	
SINGAPORE 049711		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SKS4370A	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6BM42A8G0307573	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG.	15-Apr-15	POLICY NO. :	

NATURE OF WORKS

NO	DESCRIPTION	QTY	Unit Price	Disc %	1st	Supp	PARTS NO	REVISED	PRICES
1	FRONT BUMPER / CRU	1	1,083.30	-			MBHR3-50-031BBB		1,083.30
2	RETAINER RH FRT / MC	1	19.70	-			MBHN1-50-0T1F		19.70
3	NUT,CLIP / MC	10	3.70	-			MC274-50-133		37.00
4	FASTENER / MC	2	3.00	-			MB45A-56-146A		6.00
5	GROMMET,SCREW / MC	2	2.90	-			MGHP9-50-0Z5		5.80
6	FRONT FENDER RH / DD	1	350.60	-			MB45A-52-111B		350.60
7	STAY FENDER RH FRT / ? X nn	1	37.40	-			MB4ZA-52-1R0A		37.40
8	MUD GUARD RH FRT / ? X nn	1	101.90	-			MB45A-56-130H		101.90
9	FASTENER / ? X nn	10	3.00	-			MB45A-56-146A		30.00
10	WHEEL,DISC 16X6.5 ALUM / X nn	1	1,156.80	-			M9965-D0-6560		1,156.80
11	VALVE,AIR TYRE / X nn	1	6.70	-			M9963-60-4140		6.70
12	FRONT ABSORBER RH / X nn	1	360.80	-			MBHS2-34-700A		360.80
13	BEARING TOP FRT ABSORBER RH / X nn	1	55.80	-			MB45A-34-38XA		55.80
14	RUBBER MOUNTING ABSORBER FRT RH / X nn	1	96.50	-			MKD35-34-380C		96.50
15	KNUCKLE FRT RH / X nn	1	402.60	-			MB45A-33-021		402.60
16	HUB WHEEL BEARING FRT RH / X nn	1	568.80	-			MB45A-33-04X		568.80
17	HEADLAMP RH / ? X nn	1	2,357.30	-			MBHT6-51-031A		2,357.30
18	FASTENER / ? X nn	1	3.50	-			MB092-51-833		3.50
							TOTAL PARTS		6,680.50
							TOTAL PARTS COST		6,680.50

SUPPLEMENTARY

NO	DESCRIPTION	QTY		1st	Supp	PARTS NO	REVISED	PRICES
1								
2								
3								
							TOTAL PARTS	-
							TOTAL PARTS COST	-

Labour Description

		REVISED	PRICES
1	TO REPLACE FRONT BUMPER,FRONT FENDER RH AND REPAIR FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS.	1320	2,640.00

2		TO RESPRAY FRONT BUMPER, FRONT FENDER RH AND FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS.	1370 1870 ✓	2,520.00
3	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.	X	660.00
4	MZ-BR-WHEEL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	560.00 ✓
5	MZ-BR-WHEEL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT	120.00 X
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 ✓	250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 ✓	300.00
8	MZ-BR-SUNDRI	SUNDRIES.	20 ✓	50.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES

TOTAL LABOUR	-	7,100.00
TOTAL PARTS	-	6,680.50
TOTAL	-	13,780.50
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	13,780.50
GST 7%	-	964.64
GRAND TOTAL	-	14,745.14

SUPPLEMENTARY LABOUR DESCRIPTION

			REVISED	PRICES
1		#N/A		
2		#N/A		

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES

TOTAL LABOUR	-	-
TOTAL PARTS	-	-
TOTAL	-	-
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

Steve CLKK)
3/11/21, 11:30a

Wm PL
PIP
My Play
S dy S

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: