



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
GARY KHO HOE SIANG  699C HOUGANG STREET 52 #04-37 SINGAPORE 533699  <b>Contact No</b> Mobile: 91771134	<b>Cust No/Name</b>	/GARY KHO HOE SIANG
	<b>Reg No/Reg Date</b>	SMU1822Z / 30/07/202
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	KNAF3416ML5062881
	<b>Engine No</b>	G4FGKH739382
	<b>Make/Model</b>	KIA/CERATO 1.6 A EX G333
	<b>Colour/Trim</b>	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	02/11/2021/ 17:58	TLE	261 / Edwin Caina	41981			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1900.00
RENEW RR BUMPER & RR BUMPER BODY KIT								
E PNT98000								1600.00
RESPRAY RR BUMPER & RR BUMPER BODY KIT								
A 54900099								80.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								300.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								100.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								220.00
SUPPLY REVERSE SENSOR								
M SUNDRY								50.00
Sundries								
M COVER-RR BUMPER					1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR					1.00	241.00	00.00	241.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M STAY-RR BUMPER LH					1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH					1.00	65.00	00.00	65.00
M NEW K3 2020 STEEL GRAY KLG					1.00	1721.00	00.00	1721.00
SURVEYOR NAME : _____								
SURVEYOR SIGNATURE : _____								
DATE : _____								
REMARKS : _____								
_____								

Confirm &amp; accepted by

	<b>Nett</b>	<b>7,311.00</b>
7% GST on	7311.00	<b>511.77</b>
<b>Total Payable</b>		<b>7,822.77</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.