



SURVEYORS & ADJUSTERS

TO : A L Motorwerkz

PAGEs : 3

DATE : 21.09.2021

OUR REF : ARC/2021-021

REFERENCE & PARTICULARS

VEHICLE : FBN 5073J
INSURED OWNER : KELVIN TAN PONG SIANG
POLICY NO : NA
CLAIM NO : NA
ACCIDENT DATE : 01.09.2021 1150HR

THIRD PARTY CLAIM

INSPECTION REQUESTED : OWNER
ASSIGNMENT DATE : 12.09.2021
SUM INSURED : NA
EXCESS AMOUNT : NA

PARTICULARS OF DAMAGED VEHICLE:

MAKE/MODEL : YAMAHA SNIPER T150
YEAR : 2018
CAPACITY : 150cc
ENGINE NO : G3E6E0433293
CHASIS NO : MH3UG0740J0126193
PRE-ACCIDENT STATUS : GOOD
STEERING : GOOD
BRAKES : GOOD
MILEAGE : TBA
COLOUR : BLACK

TYRE CONDITION : SIZE (FRONT):- SIZE (REAR):-

FRONT REMAINING THREADS :-

REAR REMAINING THREADS :-

GENERAL DESCRIPTION OF DAMAGE :

Font and body damages

INSPECTION DETAILS

SURVEY HELD AT : 25 Kaki Bukit Road 4
#03-62 Singapore (417800)

PHOTOGRAPHS : 65


INSPECTION DATED : 13.09.2021

REMARKS : (SUBJECT TO POLICY CONDITION)

THIS SURVEY WAS CONDUCTED STRICTLY "WITHOUT PREJUDICE"
ESTIMATED NORMAL PERIODS OF REPAIRS (7) WORKING DAYS

IN ACCORDANCE WITH YOUR INSTRUCTIONS, WE HAVE
AUTHORISED REPAIRS. (This estimate covers visible damages only.

Should there be any discrepancy or unseen items in this survey, kindly notify the





SURVEYORS & ADJUSTERS

VEHICLE NO : FBN 5073J POLICY NO :
CLAIM NO : OUR REF : ARC/2021-021

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	QTY	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION	
PARTS						
1	1	Front body faring complete set	Grazed	715.00	643.50	
2	1	Front wheel fender	Grazed	156.00	140.40	
3	1	Front Headlamp assy	Grazed	585.00	526.50	
4	1	Front RHS lamp	Grazed	364.00	327.60	
5	1	Front RHS lamp fairing	Grazed	325.00	292.50	
6	1set	Front Po lamp	Grazed	273.00	245.70	
7	1	RHS mirror	Grazed	123.50	111.15	
8	1	Handle bar	Damaged	455.00	409.50	
9	1set	Handle bar grips	Grazed	65.00	58.50	
10	1set	Handle bar balancer	Grazed	97.50	87.75	
11	1	Clutch lever	Bent	71.50	64.35	
12	1	Brake lever	Bent	123.50	111.15	
13	1	RHS brake pedal	Bent	91.00	81.90	
14	1	RHS Foot rest (pillion) bracket	Damaged	97.50	87.75	
15	1	RHS Foot rest	Bent	54.60	49.14	
16	1	Horn cover	Damaged	143.00	128.70	
17	1	Exhaust silencer	Grazed	1430.00	1,287.00	
18	1	Exhaust silencer tail cover	Grazed	156.00	140.40	
				5,326.10	less 10%	4,793.49
SPECIAL NETT ITEMS						
19	x	Bolts/Misc/seals (sundries)	Necessary	30.00	20.00	
20	1	Front rim	Bent	320.00	320.00	
21	1	Rear box assy	Grazed	250.00	250.00	
22	1	Front Handphone holder	Grazed	55.00	55.00	
23	1	Center basket	Bent	45.00	45.00	
24	1	Front number plate	Necessary	45.00	45.00	
25	1	Rear number plate	Bent	45.00	45.00	
TOTAL PARTS(SPECIAL NETT):				790.00		780.00
TOTAL PARTS:						5,573.49




SURVEYORS & ADJUSTERS

VEHICLE NO : FBN 5073J POLICY NO :
CLAIM NO : OUR REF : ARC/2021-021

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
<u>LABOUR</u>				
1	To remove and replace damaged parts and components		550.00	450.00
2	To remove, refix wiring system at accident damaged areas		60.00	60.00
3	Transport motorcycle to workshop for repairs		60.00	60.00
		Labour Total :	670.00	570.00
		TOTAL (PARTS & LABOUR):		6,143.49
		NETT TOTAL :		6,143.49
		AGREED AT LUMP SUM :		5,500.00











EVORS AND ADJUSTERS



ARC SURVEYORS AND ADJUSTERS

ARC SURVEYORS AND ADJUSTERS



ARC SURVEYORS AND ADJUSTERS

ARC SURVEYORS AND ADJUSTERS



ARC SURVEYORS AND ADJUSTERS
GEN
1006045



ARC SURVEYORS
GEN
534039931

ARC SURVEYORS AND ADJUSTERS
GEN
1006045



ARC SURVEYORS AND ADJUSTERS
GEN
1006045


ARC SURVEYORS AND ADJUSTERS
GEN
1006045

VEYORS AND ADJUST
UEN
534039931

VEYORS AND ADJUSTERS
UEN
534039931

VEYORS AND ADJUSTERS
UEN
534039931

VEYORS AND ADJUSTERS
UEN
534039931



VEYORS AND ADJUSTERS
UEN
534039931

VEYORS AND ADJUSTERS
UEN
534039931

