



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 5073J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SET FRONT BODY FAIRING COMPLETE	GRAZED	715.00	495.00
1	FRONT WHEEL FENDER	GRAZED	156.00	156.00
1	FRONT HEADLAMP ASSY	SERVICEABLE	585.00	-
1	FRONT RHS LAMP	GRAZED	364.00	150.00
1	FRONT RHS LAMP FAIRING	GRAZED	325.00	70.00
1	SET FRONT PO LAMP	GRAZED	273.00	190.00
1	RHS MIRROR	GRAZED	123.50	75.00
1	HANDLE BAR	BENT	455.00	150.00
1	SET HANDLE BAR GRIP	GRAZED	65.00	20.00
1	CLUTCH LEVER	BENT	71.50	40.00
1	BRAKE LEVER	BENT	123.50	65.00
1	RHS BRAKE PEDAL	BENT	91.00	65.00
1	RHS FOOT REST (PILLION) BRACKET	SCRATCHED	97.50	97.50
1	RHS FOOT REST	BENT	54.60	54.60
1	HORN COVER	SERVICEABLE	143.00	-
1	EXHAUST SILENCER COVER	GRAZED	1,430.00	100.00
1	EXHAUST SILENCER TAIL COVER	GRAZED	156.00	70.00
1	SET HANDLE BAR BALANCER	GRAZED	97.50	40.00
	LESS 10% DISCOUNT		-	-183.81
			5,326.10	1,654.29
<b><u>SPECIAL NETT ITEMS</u></b>				
1	BOLTS / MISC / SEALS (SUNDRIES) (SN)	NECESSARY	30.00	20.00
1	FRONT RIM (SN)	TO REPAIR SEE LABOUR	320.00	-
1	REAR BOX ASSY (SN)	GRAZED	250.00	150.00
1	FRONT HANDPHONE HOLDER (SN)	GRAZED	55.00	30.00
1	CENTER BASKET (SN)	SERVICEABLE	45.00	-
1	FRONT NUMBER PLATE (SN)	NECESSARY	45.00	25.00
1	REAR NUMBER PLATE (SN)	BENT	45.00	25.00
			790.00	250.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT RIM.		550.00	150.00
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS.		60.00	20.00
	TRANSPORT MOTORCYCLE TO WORKSHOP TO REPAIRS.		60.00	50.00
			670.00	220.00
	<b>GRAND TOTAL</b>		<b>6,786.10</b>	<b>2,124.29</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,700.00</b>

Report Ref No. CS3/LPC21009565/Vtf3e2-1

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.