



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21008543/Gtf3e2-1	Date: 29/11/2021
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 4716H	Veh. Inspected	SLA 9752G	
Policy No.	Z/21/VC00/110454	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024848	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA AERAS 2.4	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ACR500091863	Colour	BLACK	
Odometer	139392 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	HABILEAD	6 mm	
L/H Front Tyre	215/55 R17	HABILEAD	6 mm	
R/H Rear Tyre	215/55 R17	HABILEAD	6 mm	
L/H Rear Tyre	215/55 R17	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/08/2021	Inspection Date	16/08/2021	
Survey held at	14 amk st 63 blk B			
Repairer	ASSURE AUTO ASSIST PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	