

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT STRIDES AUTOMOTIVE SERVICES PTE LTD CS3/SMR21011227/T1uf3e2 Ref: 60 WOODLANDS INDUSTRIAL PARK Date: 09/11/2021 E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHF 48L SCX 3359J Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. TAX/10/21/2073 Excess (\$) 0.00 **HUA YEN Assign Date** 03/11/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA CIVIC EXI 4M Make & Model 1493 C.C HIDDEN 1999 Engine No. Year of Reg. JHMEK3550XS202302 GREEN Chassis No. Colour 377457 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/50 R15 BRIDGESTONE 6 mm L/H Front Tyre 195/50 R15 BRIDGESTONE 6 mm 195/50 R15 BRIDGESTONE R/H Rear Tyre 6 mm BRIDGESTONE L/H Rear Tyre 195/50 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S, FRONT O/S PORTION AND UNDERCARRIAGE. 5. **General Information** 31/10/2021 Inspect Date / Time 03/11/2021 (04:59 PM) Accident Date ALPHA CAR SERVICES PTE LTD Survey held at BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$6,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/SMR21011227/T1uf3e2

Inspected By

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

7 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser