

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

Not Authorize Date of Accident: 01/11/2021
 Repair By paint Your Insured
 32 days Vehicle No: YP 1808A
 61 Lp @ 19,400/h

ESTIMATE REPAIR COSTS TO TOYOTA SIENTA REG. NO. : SMN 4851 G

			SS\$	
1pc	R	Tailgate	R 1076.60	✓
1pc	R	Logo Emblem	R 75.30	✓
1pc	R	Emblem 'HYBRID'	R 61.80	✓
1pc	R	Tailgate O/S Reflector	R 235.20	X
1pc	R	Tailgate Upper Lock	} R 470.60	✗
1pc	R	Tailgate Lower Lock		
2pcs	R	Tailgate Absorber (\$217.70/pc)	R 435.40	X
1pc	R	Tailgate Inner Lock Holder	R 34.60	✓
2pcs	R	Tailgate Hinges (\$69.60/pc)	R 139.20	X
1pc	R	End Panel Outer	R 374.40	✓
1pc	R	Spare Tyre Panel	R 839.80	✓
1pc	R	End Panel Garnish	R 208.50	✓
1pc	R	O/S/R Panel	R 1014.40	✓
1pc	R	O/S/R Panel Garnish	R 721.10	X
1pc	R	O/S Taillamp Cover Panel	R 488.20	X
2pcs	R	Taillamp @ 389.10	R 975.00	✓
1pc	R	O/S/R Panel Inner Shield	R 92.70	X
1pc	R	O/S Taillamp Panel	R 224.40	X
1pc	R	Tailgate Rubber	R 386.90	✓
1pc	R	Spare Tyre Board	R 464.90	✓
1pc	R	Exhaust Pipe	R 595.50	✓
1pc	R	Rear Bumper	R 482.20	✓
1pc	R	Rear Bumper O/S Side Garnish	R 122.80	✓
1pc	R	Rear Bumper Centre Garnish	R 180.70	✓
1pc	R	Rear Bumper O/S Retainer	R 92.80	✓
1pc	R	Taillamp O/S Bracket	R 112.20	X
1pc	R	Rear Bumper O/S Reflector	R 54.40	✓
1pc	R	Rear End Panel Inner 544.60	R 735.50	✓
1pc	R	Member Floor Panel	R 388.20	✓
2pcs	R	Rear Glass Moulding RH & LH (\$39.60/pc)	R 79.20	X
1pc	NS	N/S/R Panel	R 1014.40	✓
1pc	NS	N/S/R Panel Garnish	R 721.10	X
1pc	NS	N/S/R Panel Garnish Lower	R 130.20	✓

13028.20

WIDE PAGE
 BACK

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive


#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

**ESTIMATE REPAIR COSTS TO TOYOTA SIENTA REG. NO. : SMN 4851 G**

		SS
Bal c/f		13028.20
1pc	N/S/R Door <i>1161.70</i>	<i>B1</i> 1533.30 ✓
1pc	N/S/R Door Handle	<i>nd</i> 113.10 ✓
1pc	N/S/R Door Cover	<i>nd</i> 32.90 ✓
1pc	N/S/R Door Garnish (Front)	<i>nd</i> 128.80 ✓
1pc	N/S/R Door Window Garnish	<i>nd</i> 75.80 X
1pc	N/S/R Door Lock <i>380.40</i>	<i>nd</i> 620.80 ✓
1pc	N/S/R Door Garnish (Back)	<i>nd</i> 208.30 ✓
1pc	N/S/R Door P/W Motor <i>430.10</i>	<i>nd</i> 721.30 X
1pc	N/S/R Door P/W Motor Regulator	<i>nd</i> 201.90 X
1pc	Lower Roller	<i>nd</i> 301.40 X
1pc	Upper Roller	<i>nd</i> 101.90 X
1pc	Slide Door Center Rail	<i>nd</i> 274.90 X
1pc	Center Rail Guide (Rubber)	<i>nd</i> 166.60 X
1pc	N/S/R Door Sliding Door Motor	<i>nd</i> 899.80 X
1pc	N/S Rocker Panel	<i>nd</i> 424.70 X
1pc	N/S Centre Pillar	<i>nd</i> 367.80 X
1pc	N/S 'A' pillar	<i>nd</i> 336.20 X
1pc	N/S/R Door Catch	<i>nd</i> 41.30 X
1pc	N/S/F Door	<i>B1</i> 1181.10 ✓
1pc	N/S Wing Mirror <i>866.10</i>	<i>nd</i> 1157.70 ✓
1pc	N/S/F Door Handle	<i>nd</i> 113.10 ✓
1pc	N/S/F Door Handle Cover	<i>nd</i> 32.90 ✓
1pc	N/S/F Door Rubber	<i>nd</i> 221.80 ✓
1pc	N/S/F Door Window Glass	<i>Shatterd</i> 543.30 ✓
1pc	N/S/F Door Outer Moulding	<i>nd</i> 93.90 ✓
1pc	N/S/F Door Garnish	<i>nd</i> 138.40 ✓
1pc	N/S/F Door Run Channel	<i>nd</i> 109.90 ✓
1pc	N/S/F Door 1/4 Glass	<i>nd</i> 193.30 X
1pc	N/S/F Door 1/4 Glass Stand	<i>nd</i> 88.70 ✓
1pc	N/S/F Door Trim <i>800.30</i>	<i>nd</i> 1182.20 X
2pcs	N/S/F Door Hinges	<i>Top B1</i> 171.60 ✓
1pc	N/S/F Door Check	<i>nd</i> 123.30 X
1pc	N/S/F Door Lock	<i>nd</i> 567.30 ✓
1pc	Dashboard	<i>nd</i> 1105.60 ✓

(\$85.80/pc)

Whole rep
N/S portion

26603.10

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

ESTIMATE REPAIR COSTS TO TOYOTA SIENTA REG. NO. : SMN 4851 G

S\$

Bal c/f	26603.10		
1pc N/S/F Pillar Rubber	148.40	X	} N/S portion
1pc N/S/F Fender 634.40	708.90	✓	
1pc N/S/F Fender Inner Shield	187.10	✓	
1pc N/S Headlamp	1159.10	✓	
1pc Front Bumper	486.70	✓	
1pc Front Bumper LH Retainer	68.10	✓	
1pc Front Bumper LH Outer Garnish	108.80	✓	
1pc N/S/F Absorber	532.30	✓	
1pc N/S/F Knuckle Arm	336.90	✓	
1pc N/S/F Bearing	161.20	✓	
1pc N/S/F Bearing Hub	239.70	✓X	
1pc N/S/F Lower Arm 616.70	989.50	✓	
1pc N/S/F Tie Rod	141.60	X	
1pc Stabilizer Link	177.10	X	
	32048.50		
Less : 25%	8012.13		
	24036.37		

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

ESTIMATE REPAIR COSTS TO TOYOTA SIENTA REG. NO. : SMN 4851 G

					S\$	
Bal c/f					24036.37	
LABOUR & MISC CHARGES						
Panel Knocking	new	2000	n/s	1200	4500.00	3200
Spray Painting	5	1200	4	1200	2800.00	2400
Wire Checking	5	20	2	20	100.00	40
Towing	n/s				80.00	50
Labour to Remove Tailgate Glass		R			180.00	120
Sealant & Clip	R				80.00	—
Inner Seal	R				60.00	—
Labour to Remove 2 door Attach Parts & Door Trims			n/s		320.00	120
Labour to Remove 2 Rear Panels Quarter Glass			n/s		300.00	160
Sealant (2x)	n/s	40	new	40	160.00	80
Labour to Remove N/S/F Door 1/4 Glass			n/s		80.00	40
Labour to Remove Interior Upholstery & Roof Lining to Facilitate Repair			R		500.00	150
Labour to Repair & Replace DashBoard			n/s		350.00	250
Reset Airbag System			n/s		250.00	X
Computerised Wheel Alignment			n/s		160.00	60
Labour to Remove & Refix Under Carriage			n/s		360.00	200
2 Wheel Cap (\$45/pc)			n/s	new	90.00	4
2 Steel Rims (\$150/pc)			n/s		300.00	X
TOTAL					34706.37	

HWA SENG SPRAY PAINTING PTE LTD



HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

ESTIMATE REPAIR COSTS TO TOYOTA SIENTA REG. NO. : SMN 4851 G

S\$

SUPPLEMENTARY PARTS

1pc	N/S/F Door Motor	458.20	} n/s	763.30	—
1pc	N/S/F Door Regulator			290.60	—
1pc	N/S/R Door Weather Strip	223.40		699.80	—
1pc	Exhaust Pipe Shield		→ (Recor)	175.00	✓
				1928.70	
				Less : 25%	482.18
				TOTAL	1446.52

HWA SENG SPRAY PAINTING PTE LTD

