

ASS. REC. BY: Tan J HREF: CS/CT1210/1238/Tiny3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: SLF 2211XPolicy No. DMPCSNW00189692101Claims No. SNM21D206249/C02/TOHHS

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$180K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SBM 70E Yr Regn: 2016, OCTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X6 SR C.C. 2979Colour Black A/C: Insured / Std / NI / NASp. Reading 163041 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAK4220800P5710Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 325/30R21R: u u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 31/10/2021 D.O.I. 10/11/21Survey held at Pico 60Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/6/22 LS \$16,500 (Red 70,574.16, 81%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 15/6/22-typist

Report Format: MerimenLump Sum / L.S. (\$) \$16,500Days Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

# RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd  
Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875  
Email: claims@rico60.com  
Tel: 6286 6060 Fax : 6286 7060

## RICO Office Use Only

Parts -%10	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	92k

TO: china taiping

Vehicle No : SBM 70 E

Make & Model : BMW X6

DATE: 2/11/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BONNET	1	\$ 1,850.00	\$ 1,850.00
2	BONNET RUBBER SEAL	1	\$ 56.00	\$ 56.00
3	BONNET LOGO	1	\$ 125.00	\$ 125.00
4	BONNET LOWER SIDE LOCK	2	\$ 321.00	\$ 642.00
5	BONNET SIDE LOCK CATCH	2	\$ 100.00	\$ 200.00
6	FRONT BUMPER	1	\$ 2,624.00	\$ 2,624.00
7	FRONT BUMPER TOP SEAL	1	\$ 120.00	\$ 120.00
8	FRONT BUMPER SIDE RETAINER	2	\$ 219.00	\$ 438.00
9	FRONT BUMPER SPRAY NOZZLE	2	\$ RHx 466.00	\$ 932.00
10	FRONT BUMPER SPRAY NOZZLE COVER	2	\$ RH 56.40	\$ 112.80
11	FRONT BUMPER CENTER GRILLE	1	\$ 377.80	\$ 377.80
12	FRONT BUMPER SIDE GRILLE	2	\$ 324.00	\$ 648.00
13	FRONT BUMPER REINFORCEMENT	1	\$ 688.40	\$ 688.40
14	FRONT BUMPER SPONGE	1	\$ 347.00	\$ 347.00
15	FROTN BUMPER INNER SIDE AIR ARCH	2	\$ 168.00	\$ 336.00
16	FROTN BUMPER SIDE AIR ARCH INNER	2	\$ 190.00	\$ 380.00
17	FRONT BUMPER SIDE COVER	2	\$ 325.20	\$ 650.40
18	FRONT BUMPER SIDE COVER MOULDING	2	\$ 224.00	\$ 448.00
19	FRONT BUMPER UNDER COVER	2	\$ 485.00	\$ 970.00
20	FRONT BUMPER PARKING SENSOR	3	\$ 389.00	\$ 1,556.00
21	FRONT PARKING SENSOR WIREHARNESS	1	\$ 845.00	\$ 845.00
40	FRONT PARKING CAMERA 360	1	\$ 1,542.00	\$ 1,542.00
22	FRONT FOG LAMP	2	\$ 658.00	\$ 1,316.00
23	FRONT CAR PLATE GARNISH	1	\$ 255.00	\$ 255.00
24	FRONT GRILLE	2	\$ 377.00	\$ 754.00
25	FRONT GRILLE INNER AIR ARCH	1	\$ 689.00	\$ 689.00
26	HEADLAMP	2	\$ 2,987.30	\$ 5,974.60
27	HEADLAMP LOWER SUPPORT BEAN	2	\$ 145.00	\$ 290.00
28	SUPPORT PANEL	1	\$ 1,189.00	\$ 1,189.00
29	SUPPORT PANEL TOP GARNISH	1	\$ 369.00	\$ 369.00
30	SUPPORT PANEL TOP RUBBER	1	\$ 244.00	\$ 244.00
31	AIR CONDENSER	1	\$ 1,233.00	\$ 1,233.00

Like 7dudi

bt -  
na -  
na -  
x  
x  
de -  
x  
de -  
x LH de -  
x LH de -  
cua -  
cua -  
bc -  
ca -  
cua -  
cua -  
cua -  
cua -  
x  
dys -  
fy -  
dys -  
cua -  
xnt -  
cua -  
cua -  
xna -  
xna -  
x  
x  
x



32	RADIATOR	1	\$ 1,527.50	\$ 1,527.50	X
33	RADIATOR FAN MOTOR ASSY	1	\$ 1,542.00	\$ 1,542.00	X
36	FRONT FENDER	2	\$ 1,320.50	\$ 2,641.00	X
37	FRONT FENDER ARCH GARNISH	2	\$ 677.00	\$ 1,354.00	de -
39	FRONT FENDER INNER COWLING (FRONT)	2	\$ 298.20	\$ 596.40	X fu -
40	FRONT FENDER INNER COWLING (REAR)	2	\$ 214.00	\$ 428.00	X
42	DRIVER SEAT BELT	1	\$ 1,412.00	\$ 1,412.00	aut -
43	PASSENGER SEAT BELT	1	\$ 1,421.00	\$ 1,421.00	aut -
45	SRS AIRBAG CONTOR UNIT	1	\$ 1,864.00	\$ 1,864.00	aut -
47	TAILGATE	1	\$ 2,548.00	\$ 2,548.00	de
48	TAILGATE LOGO	1	\$ 125.00	\$ 125.00	gr -
50	TAILGATE EMBLEM (X6)	1	\$ 97.30	\$ 97.30	de -
51	TAILGATE WINDSCREEN INNER SEAL	1	\$ 154.00	\$ 154.00	X
53	TAILGATE REVESE CAMERA	1	\$ 650.00	\$ 650.00	X
55	TAILGATE LAMP	2	\$ 854.00	\$ 1,708.00	X
56	TAILGATE INNER TRIM	1	\$ 655.00	\$ 655.00	X
58	TAILGATE INNER LOCK	1	\$ 565.00	\$ 565.00	gr -
59	TAILGATE LOCK CATCH	1	\$ 46.00	\$ 46.00	X
61	TAILGATE WEATHERSTRIP	1	\$ 298.40	\$ 298.40	fu -
63	TAILGATE LOCK DETECTOR	1	\$ 317.90	\$ 317.90	X
64	REAR BUMPER	1	\$ 1,933.50	\$ 1,933.50	de -
66	REAR BUMPER SIDE BRACKET	2	\$ 278.90	\$ 557.80	X
67	REAR BUMPER CENTER BRACKET (CENTER)	1	\$ 327.50	\$ 327.50	gr -
69	REAR BUMPER REINFORCEMENT	1	\$ 883.50	\$ 883.50	X
71	REAR BUMPER TOWING COVER	1	\$ 58.00	\$ 58.00	de -
72	REAR BUMPER SENSOR	2, 4	\$ 314.00	\$ 1,256.00	nu -
74	REAR BUMPER SENSOR WIREHARNES	1	\$ 698.00	\$ 698.00	fu -
75	REAR BUMPER SENSOR HOLDER	4	\$ 31.20	\$ 124.80	gr -
77	REAR BUMPER SENSOR BRACKET	1	\$ 120.00	\$ 120.00	de -
79	REAR BUMPER DIFFUSER	1	\$ 1,004.80	\$ 1,004.80	gr -
80	REAR BUMPER DIFFUSER TOP PAD	1	\$ 698.00	\$ 698.00	de -
82	REAR BUMPER REFLECTOR	2	\$ <del>249.20</del> 249.20	\$ 498.40	fu -
83	CONTROL SMART OPENER SENSOR 2	1	\$ 384.00	\$ 384.00	dis -
85	CONTROL SMART OPENER SENSOR 1	1	\$ 526.00	\$ 526.00	dis -
87	CONTROL SMART OPENER SENSOR UNIT ECU	1	\$ 548.00	\$ 548.00	X gr -
88	TAIL LAMP	2	\$ 755.90	\$ 1,511.80	gr -
90	TAIL LAMP SIDE GARNISH	2	\$ 125.00	\$ 250.00	X
91	TAIL LAMP BOTTOM RETAINER	2	\$ 211.10	\$ 422.20	gr -
93	REAR END PANEL	1	\$ 1,542.00	\$ 1,542.00	de -
95	REAR END PANEL TOP GARNISH	1	\$ 346.00	\$ 346.00	de -
96	REAR FLOOR PANEL	1	\$ 2,370.10	\$ 2,370.10	X
98	REAR FLOOR TOP BOARD	1	\$ 845.00	\$ 845.00	gr -

99 REAR FENDER ARCH GARNISH	2	\$ 537.20	\$ 1,074.40	de
101 REAR FENDER INNER TRIM	2	\$ 685.00	\$ 1,370.00	X
103 REAR FENDER INNER SHIELD	2	\$ 219.00	\$ 438.00	X
104 REAR EXHAUST PIPE	1	\$ 2,572.30	\$ 2,572.30	Ry
106 REAR EXHAUST MOUNTING	2	\$ 60.00	\$ 120.00	X
107 REAR EXHAUST PIPE BRACKET	1	\$ 98.00	\$ 98.00	X
109 REAR EXHAUST HEAT PLATE	1	\$ 479.58	\$ 479.58	bt

Subtotal : \$ 71,210.18

Less 10% \$ 7,121.02

Parts Total : \$ 64,089.16

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT NUMBER PLATE	1	\$ 100.00	\$ 100.00 45
2	FRONT BUMPER CARBON FIBER DIFFUSER	1	\$ 3,800.00	\$ 3,800.00 1000 cur
3	FRONT BUMPER CLIPS	1	\$ 60.00	\$ 60.00 20w
4	FRONT FENDER ARCH GARNISH CLIP	1	\$ 50.00	\$ 50.00 20w
5	FRONT FENDER ARCH GARNISH RIVET	1	\$ 80.00	\$ 80.00 20w
6	FRONT FENDER INNER COWLING CLIPS SET	1	\$ 70.00	\$ 70.00 30
7	AIR HORN	1	\$ 400.00	\$ 400.00 X
8	FRONT BUMPER UNDER COVER CLIP	1	\$ 60.00	\$ 60.00 X
9	FRONT SUPPORT TOP GARNISH CLIP	1	\$ 65.00	\$ 65.00 X
10	FRONT SUPPORT PANEL SEALANT	1	\$ 80.00	\$ 80.00 X
11	FRONT GRILLE CLIP	1	\$ 50.00	\$ 50.00 20w
12	COOLANT	1	\$ 150.00	\$ 150.00 X
13	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00 X
14	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00 X
15	TAILGATE INNER TRIM CLIP	1	\$ 40.00	\$ 40.00 X
16	TAIL LAMP SIDE GARNISH CLIPS	1	\$ 50.00	\$ 50.00 X
17	TAIL LAMP CLIP	1	\$ 30.00	\$ 30.00 20w
18	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00 X
19	BOOTLID SEALANT	1	\$ 80.00	\$ 80.00 X
20	REAR FENDER ARCH GARNISH CLIP	1	\$ 50.00	\$ 50.00 20w
21	REAR FENDER INNER TRIM CLIPS	1	\$ 50.00	\$ 50.00 X
22	REAR FENDER INNER SHIELD CLIPS	1	\$ 50.00	\$ 50.00 X
23	REAR BUMPER CLIP	1	\$ 60.00	\$ 60.00 30
24	REAR BUMPER CARBON FIBER DIFFUSER	1	\$ 4,800.00	\$ 4,800.00 1000 cur
25	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 50.00 20
26	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00 30
27	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00 X
28	REAR CARBON EXHAUST HEAD SET	1	\$ 1,200.00	\$ 1,200.00 450
SPECIAL NETT			\$	12,035.00



LABOUR (FRONT)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00 500
TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00 1250 600
ADJUST AND FOCUS FRONT LED ADAPTIVE LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 650.00 30
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 250.00 X
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 250.00 X
WIRING CHECK	\$ 300.00 30
REMOVE AND REFIX FRONT PARKING CAMARE 360 AND DISTANCE SETTING	\$ 200.00 30
REMOVE AND REFIX FRONT PARKING SENSOR AND DISTANCE SETTING	\$ 150.00 30

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00 800 900
TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00 1250 800
TUFF COAT	\$ 200.00 30
WIRING CHECK	\$ 100.00 30
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00 60
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00 30
REMOVE AND REFIX REVERSE CAMARE AND DISTANCE SETTING	\$ 200.00 30
REMOVE AND INSTALL REAR WINDSCREEN	\$ 150.00 X
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART	\$ 300.00 X
CONDUCT WATER LEAKAGE TEST	\$ 150.00 X
REMOVE AND REFIX REAR EXHAUST PIPE	\$ 350.00 80
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 600.00 200

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

#### APPROVED DETAILS

NO. OF WORKING DAYS  
PART BY PART OR LUMP SUM  
DATE & TIME OF SURVEY  
SURVEYED BY  
CONTACT NUMBER  
FAX NUMBER

LABOUR TOTAL \$ 10,950.00

Total	Parts Cost	\$	76,124.16
Total	Labour Cost	\$	10,950.00
Total	Repair Cost	\$	87,074.16

Tanfahin 97495749  
WP 10/11/21 @ 1230pm  
L/S Resurvey after repair  
8 days  
Tanfahin c/ltank.com

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 287J

### Vehicle Details

Vehicle No.: SBM70E  
Vehicle to be Exported: No  
Intended Deregistration Date: 02 Nov 2021  
Vehicle Make: B.M.W.  
Vehicle Model: X6 XDRIVE35I SR LED NAV HUD  
Primary Colour: Grey  
Manufacturing Year: 2016  
Engine No.: 01199590N55B30A  
Chassis No.: WBAKU220800P55710  
Maximum Power Output: 225.0 kW (301 bhp)  
Open Market Value: \$68,263.00  
Original Registration Date: 05 Oct 2016  
First Registration Date: 05 Oct 2016  
Transfer Count: 2  
Actual ARF Paid: \$94,874.00

### Intended PARF Rebate Details


PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 04 Oct 2026  
PARF Rebate Amount: \$66,411.00

### Intended COE Rebate Details

COE Expiry Date: 04 Oct 2026  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$55,201.00  
COE Rebate Amount: \$27,170.00  
**Total Rebate Amount: \$93,581.00**

The information contained herein is correct as at 02 Nov 2021

OK



BMW X6 Price Range Depreciation 2017 Vehicle Type Search Advanced Search

Home » Used Cars » Car (S) Pte Ltd » BMW X6 xDrive35i Sunroof

## BMW X6 xDrive35i Sunroof

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD



Price	\$199,800		
Depreciation	\$27,500 /yr View models with similar depre	Reg Date	20-Apr-2017 (5yrs 5mths 10days COE left)
Mileage	61,238 km (13.4k /yr)	Manufactured	2017
Road Tax	\$2,362 /yr	Transmission	Auto
Dereg Value	\$104,548 as of today (change)	OMV	\$71,223
COE	\$54,000	ARF	\$100,202
Engine Cap	2,979 cc	Power	225.0 kW (301 bhp)
Curb Weight	2,025 kg	No. of Owners	2
Type of Vehicle	SUV		

## Features

3.0L 6-Cylinders Inline Twin-Turbo Charged, 6 Speed Auto Transmission, All Wheel Drive, Harmon Kardon Sound System, Keyless Entry, Auto Tailgate. View specs of the BMW X6

## Description

Accident Free! Original Interior In Immaculate Condition, Guaranteed Satisfaction! Competitive Interest Rates At 1.88%! Speedy Loan Application & Approval! Immediate Driveaway Available! Call/Whatsapp Our Friendly Sales Consultants To View This Perfection Today!

## Category

PARF Car, Premium Ad Car

## Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

## Resources



## sgCarMart Used Car Warranty

Get \$0 future car repair bill. Ask your dealer for a warranty on this car. Learn more



## Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare

Idle Evaluation

Shortlist  
More

Compare

Report Error

## Seller Information

## Car (S) Pte Ltd

★ PREMIUM DEALER 2021 ★

288 vehicles for sale 171 sold in past 3 mths

39 Woodlands Close #07-K1, #08-04

Mega @ Woodlands

Tel: 63863322

Search cars nearby

Ben

Winson

97387518

83802211



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	02/11/2021 12:57 (SGT)
Date of Accident	31/10/2021 14:00 (SGT)
Exact Location of Accident	Pasir Ris Drive 3, Singapore
Additional Location Information	PASIR RIS DRIVE 3 (INFRONT OF BLK 244)
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBM70E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN BOON TAT
NRIC No	SXXXX287J
Email Address	gladwin_tan@prince.com.sg
Mobile Phone No	(Phone) +65-90687128
Alternative Phone No	(Home) +65-90687128

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	X6
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2979

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5116494104-01
Cover Note Number	-

### DRIVER

Name of Driver	GLADWIN TAN WEI HONG
NRIC No	SXXXX882D



Date Of Birth	03/02/1995
Occupation	Indoor
Date Of Driving Pass	27/03/2014
Driving experience	7 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90687128
Alt. Phone Number	-
Email Address	gladwin_tan@prince.com.sg
Address	53 SUNGEI TENGAH ROAD
Address complement	-
Postcode	698998
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Parent
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	MATAWEE
Gender	Female

#### PASSENGER 2

Name	KONG YANG
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN ATTACHED.

#### ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF2211X
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKJ5864H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	GLADWIN TAN WEI HONG
Gender	Male
Phone No	(Phone) +65-90687128
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SBM70E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 2

Name of injured person	MATAWEE
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SBM70E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 3

Name of injured person	KONG YANG
Gender	Male
Phone No	-



Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SBM70E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Ben Tan  
Policyholder's Signature / Date & Time

[Signature]  
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]  
Witnessed by Reporting Centre Personnel

Sketch Plan

veh A: SBM 70 E  
veh B: SLF 2211 X  
veh C: SKJ 5864 H





Describe Circumstances of the Accident

Handwritten notes in the sketch plan area:

- Attached
- to
- Peter

**Declaration**

We declare the foregoing particulars are true in every respect.

*Ben Tan*

Policyholder's Signature / Date & Time

*[Signature]*

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

ON THE STATED DATE AND TIME. I, VEHICLE A (SBM70E) WAS TRAVELLING STRAIGHT ON THE STATED VENUE. THE FRONT VEHICLE SUDDENLY JAMMED BRAKE. I FOLLOWED SUIT AND MANAGE TO STOP IN TIME WITHOUT HAVING ANY COLLISION WITH THE FRONT VEHICLE. SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR PORTION OF MY STATIONARY VEHICLE, THE HUGE IMPACT CAUSE MY VEHICLE TO PROPEL FORWARD AND HIT ONTO VEHICLE C (SKJ5864H) REAR PORTION. AFTER I ALIGHTED I THEN REALISE THAT IS VEHICLE B (SLF2211X) THAT HAD COLLIDED ONTO MY VEHICLE. I WISH TO STATE THAT THIS IS A 3 CARS CHAIN COLLISION.

**VEHICLE A : SBM70E**

**VEHICLE B : SLF2211X**

**VEHICLE C : SKJ5864H**