



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 01/11/2021

Estimated repair cost for vehicle no: SJM9595D TOYOTA CAMRY HYBRID 2.5

CHASSIS: JTNB23HK703044517 (2019)

02/11/2021

TP 1st Cap
Xiao Tong.

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>dent</i>	\$633.25	\$633.25 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$370.90	\$370.90 +
3	1	FRONT BUMPER SPONGE <i>new</i>	\$191.10	\$191.10 +
4	1	FRONT BUMPER TOP GARNISH RH <i>new</i>	\$178.90	\$178.90 +
5	1	FRONT BUMPER SIDE RETAINER RH <i>dent</i>	\$189.10	\$189.10 ✓
6	1	FRONT BUMPER FOG LAMP COVER RH <i>lt</i>	\$230.80	\$230.80 ✓
7	1	FRONT BUMPER LOWER SIDE GARNISH RH <i>lt</i>	\$230.40	\$230.40 ✓
8	1	FRONT BUMPER CENTER GRILLE <i>new</i>	\$476.90	\$476.90 +
9	1	FRONT GRILLE <i>new</i>	\$578.40	\$578.40 +
10	1	FRONT HEADLAMP RH <i>lt</i>	\$2,721.10	\$2,721.10 ✓
11	1	FRONT HEADLAMP LOWER BRACKET RH <i>new</i>	\$220.30	\$220.30 +
12	1	FRONT FENDER RH <i>Dented</i>	\$780.10	\$780.10 ✓
13	1	FRONT FENDER INNER SHIELD RH <i>new</i>	\$370.10	\$370.10 +

Front Bumper Sensor
4985.75 *Dented*
3739.31

201 ✓
4841.4
3631.50

TOTAL : \$7,028.00
LESS 25 % \$1,757.00
SUB-TOTAL : \$5,271.00

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$ 80.00	\$ 80.00 → 30
2	1	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	\$ 60.00	\$ 60.00 +
3	1	FRONT GRILLE CLIPS <i>new</i>	\$ 50.00	\$ 50.00 +
4	1	RH FRONT SPORT RIM <i>lt</i>	\$ 2505	\$ 2505 1200

430
1230

TOTAL: \$1,390.00

TOTAL PARTS \$6,661.00

What for 2505 37

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 TO CONDUCT WHEEL ALIGNMENT

~~\$1,200.00~~ ⁵⁰⁰
~~\$1,000.00~~ ⁵⁰⁰
~~\$80.00~~ ³⁰
~~\$200.00~~ ⁴⁰
~~\$200.00~~ ⁸⁰

Subtotal :- \$2,680.00

Total:- \$9,341.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
P/P 03/11/21.

04 Days.

total: 6119.31
(P/P)

total 6119.31
(P/P)