

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : XD9005Y

Accident Date : 2/11/2021

Location : 301 PUNGGOL CENTRAL

Model:

ISUZU FXZ77M
2/4/2014

3P: XD6345K (CHINA TAIPING)

TP Chiam.

Xiao Tong.

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1		Rear tailgate <i>Dented.</i>		13,000.00	2500
		Sub-Total:	0.00	13000.00	0.00
			25%	0%	10%
		After Less %:	0.00	13000.00	0.00
		Labour			
1		To remove and replace rear tail gate		1,000.00	400
2		To spray painting.		600.00	300
		Sub-Total:		1,600.00	
		Total:		14,600.00	
		After Less 20%:		11,680.00	700

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Whd: 3200

H/s: 2SK.

02 Days.



8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: