

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5495L*Not Authored*

AAD2111-004

*Accuracy B4 point**05879.15*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5495L

JTDKB3FU703092365

TOYOTA

PRIUS GEN 4

29/10/2021

AIG

30/06/2021

02 NOV 2021**PART**

- 1 COVER, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 RIM

*977.80 BT ✓***LIST**

\$	<i>Bu/100</i>	521.00	✓
\$	<i>SL</i>	110.50	X
\$	<i>RL</i>	716.60	X
\$	<i>SL</i>	80.20	X
\$	<i>DIS</i>	80.10	✓
\$	<i>SL</i>	120.10	X
\$	<i>SL</i>	30.20	X
\$	<i>GR</i>	95.60	✓
\$	<i>SL</i>	422.50	X
\$	<i>SL</i>	178.60	X
\$	<i>SL</i>	105.80	X
\$	<i>SL</i>	219.10	X
\$	<i>Mgmt</i>	2,637.60	✓
\$	<i>SL</i>	1,436.60	X
\$	<i>RL</i>	1,900.10	✓

TOTAL \$ 8,654.60**25% \$ 2,163.65****\$ 6,490.95****Special Nett**

- 1 TYRE
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1 FENDER LINER CLIP
- 1 FENDER CLIP

\$	<i>SL</i>	350.00	X
\$	<i>RL</i>	95.00	<i>505.00</i>
\$	<i>RL</i>	85.00	X
\$	<i>RL</i>	65.00	X
\$	<i>RL</i>	70.00	X

TOTAL \$ 595.00**TOTAL PARTS \$ 7,085.95**

Trans-cab Auto Services Pte Ltd**AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5495L**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	<i>400/</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>4</i>	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>4</i>	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i>	380.00	X
To check steering geometry and computer wheel alignment	\$		220.00	<i>60/</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	<i>30/</i>
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>440/</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>20/</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$		220.00	<i>20/</i>

Trans-cab Auto Services Pte Ltd**AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5495L

To remove and refit radiator support cross-member and other
necessary items to enable bodywork repair.

\$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ *nn* 380.00 X**TOTAL \$ 8,670.00****Over All Total \$ 15,755.95****(PART-BY-PART) Repair Days***25 DAYS*
*2 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**