



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21011246/Uqf3n2 Date: 18/11/2021 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLJ 9943A	Veh. Inspected	SKL 777Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103241/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	03/11/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA CAMRY HYBRID (A)	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	AXVH701034877	Colour	BLUE	
Odometer	46597 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/45 ZR18	MICHELIN	7 mm	
L/H Front Tyre	235/45 ZR18	MICHELIN	7 mm	
R/H Rear Tyre	235/45 ZR18	MICHELIN	7 mm	
L/H Rear Tyre	235/45 ZR18	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/10/2021	Inspection Date	08/11/2021	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	