

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21011251/KQY3Q2**Date:** 27/02/2023**REFERENCE**

Insured/Claimant: RABBIT CAR RENTAL PTE LTD Policy No: DMHCSNA00004272000

Date of Loss: 29/08/2020

Nature of Claim: OD

Claim No: SNM20D203135/C01/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLE2371Y**  
 Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4034840  
 Reg. Date: 14/07/2016 (Man. Year: 2016) Chassis No: RU11114835  
 Colour: Metallic Black Odometer: 0 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: S\$53,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Roadstone 2 mm Rear Left Side: Firenza 8 mm  
 Front Right Side: Roadstone 2 mm Rear Right Side: Firenza 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	31,183.00	21,868.00	9,315.00	29.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,978.20	1,818.80	159.40	8.06
Paintwork Labour	706.88	680.60	26.28	3.72
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>33,868.08</b>	<b>24,367.40</b>	<b>9,500.68</b>	<b>28.05</b>
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	33,868.08	22,367.40	11,500.68	33.96
<b>+ GST 7.00/7.00% (S\$)</b>	2,370.77	1,565.72	805.05	33.96
<b>Nett Amount (S\$)</b>	<b>36,238.85</b>	<b>23,933.12</b>	<b>12,305.73</b>	<b>33.96</b>

**INSPECTION**

Date of Assignment: 03/11/2021 Present Location: Ding Auto Pte Ltd (HQ)  
 BLK 10 #01-20 SIN MING IND EST SEC C  
 Date Inspected: 05/11/2021 Inspected At: SINGAPORE 575645  
 Repairer: Ding Auto Pte Ltd (HQ)  
 Estimated Period of Repair: 28.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$7,750.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE2371Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		31,183.00 F	*21,868.00 F
						F=Franchise part.
Total Parts (\$\$)					31,183.00	21,868.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	470.40	449.40
2	Total Paint Materials	New	236.48	231.20
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	1,978.20	1,818.80
Gross Labour Cost (S\$)			2,685.08	2,499.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >