

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 08 Nov 2021

Preliminary Advice

Vehicle No	: SLE2371Y	Accident Date	: 29/08/2020
Make	: HONDA VEZEL	Policy No.	: DMHCSNA00004272000
Assignment Date	: 03/11/2021	Excess	: S\$2,000.00
Date of Inspection	: 05/11/2021	Est. Duration of Repair	: 28
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,868.08
Revised Amount	:S\$	24,367.40
Check Items (Estimated)	:S\$	7,750.00
Total	:S\$	32,117.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	28,425.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,575.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending for repair cost from repairer.