

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD367B

AADD2111-

Not Notified
11 Sep @ 1050h

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD367B
VF1ABL15AUC282736
RENAULT
LATITUDE
31/10/2021
CHINA
17/05/2016

02 NOV 2021

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel)TRIM

LIST

\$	R	561.70	X
\$	<i>Adl</i>	411.90	✓
\$	Sn	98.10	X
\$	Sn	82.10	X
\$	Sn	59.80	X
\$	Sn	80.80	X
\$	Sn	54.20	X
\$	Bl	547.80	✓
\$	R	745.80	X
\$	Sn	404.56	X
\$		3,046.76	
10% \$		304.68	
\$		2,742.08	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP

\$	Sn	700.00	X
\$	nn	66.00	X
\$	nn	33.00	X
\$	nn	10.00	X
\$	nn	20.00	X
\$	nn	10.00	X
\$	nn	20.00	X
\$	nn	66.00	✓
TOTAL	\$	925.00	
TOTAL PARTS	\$	3,667.08	

LABOUR

Trans-cab Auto Services Pte Ltd

AADD2111-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD367B

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	1501
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To Check Electrical Lighting Concerned.	\$	~ 170.00	X

TOTAL \$ 7,580.00

Over All Total \$ 13,989.17

**(LUMP SUM)
Repair Days**

**20 DAYS
1 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: