

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD367B**

**AADD2111-**

*Not Authorized*  
*U/Smp &*

Vehicle No.:	<b>SHD367B</b>
Chassis No.:	VF1ABL15AUC282736
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	31/10/2021
Third Party Insurer :	<b>CHINA</b>
Date of Registration :	17/05/2016

**PART**

		<b>LIST</b>	
1 BUMPER COVER REAR	\$	R 561.70	X
1 BUMPER LOWER REAR	\$	Nett Wt 411.90	✓
1 BUMPER BRACKET CTR REAR	\$	Sm 98.10	X
1 BUMPER BRACKET SIDE RH REAR	\$	Sm 82.10	X
1 BUMPER RETAINER RH REAR	\$	Sm 59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	Sm 80.80	X
1 BUMPER RETAINER LH REAR	\$	Sm 54.20	X
1 BUMPER BEAM REAR	\$	547.80	7
1 OUTER PANEL REAR (End Panel)	\$	R 745.80	X
1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56	X
	\$	<b>3,046.76</b>	
To transfer of rear windscreen fittings and conduct water leakage test	10% \$	<b>304.68</b>	
	\$	<b>2,742.08</b>	

**Special Nett**

1SET PARKING AID	\$	Sm 700.00	X
1SET REAR BUMPER CLIP	\$	nn 66.00	X
1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn 66.00	✓
<b>TOTAL</b>	\$	<b>925.00</b>	
<b>TOTAL PARTS</b>	\$	<b>3,667.08</b>	

**LABOUR**

**Trans-cab Auto Services Pte Ltd**

AADD2111-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD367B**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	1501
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To Check Electrical Lighting Concerned.	\$	~ 170.00	X

**TOTAL \$ 7,580.00**

**Over All Total \$ 13,989.17**

**(LUMP SUM)**

**Repair Days**

**20 DAYS**  
*1 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer