

BMW SERVICE CENTRE

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

Estimate No. : 21998810
Date Estimated : 02/11/2021
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Chan Tee Seng

- ACCOUNT -
China Taiping Insurance (S)
Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Motor Claims Department

REGN. NO.
SGQ3579E

CHASSIS NO.
WW96727

REGN. DATE MODEL
18/12/2020 520

DESCRIPTION	ORIGINAL PRICE	NETT
To make good the rear bumper, rear RH fender, rear RH door include removing attachments to facilitate repairs and knocking out dents caused by the accident		2,880.00
To spray paint rear bumper, rear RH fender, rear RH door and rear RH handle		1,962.50
To replace rear RH door handle mechanism include conducting checks on all door sensors and central locking system for proper function		360.00
To check electrical wiring systems and lightings include resetting and checking airbags for proper function		120.00
Sundries		80.00

DESCRIPTION	UNIT	PRICE	QTY	NETT
51 21 9491462 Door handle, prime		96.90	1.00	96.90

Total Labour :	5,402.50
Total Parts :	96.90
Total Labour & Parts :	5,499.40
Deduction for Excess :	
Total Repair Costs less Exc	5,499.40
GST @7%:	384.96
Grand Total :	5,884.36