

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

library
clean

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2100285
Date: 02 Nov 2021
Veh Reg No: SLM6345E
Make/Model: HONDA SHUTTLE 1.5G CVT
Chasis No: GK81102211
Reg. Date: 04/04/2017
Your Ref No: SFG1730L

Claim Type: Third Party
Accident Date: 11/09/2021
TP Veh Reg No: SFG1730L

Xiao Tony

Estimate Repair Cost to Vehicle No :SLM6345E

Quantity	Description	List Price	Amount
	List Price	<u>SS</u> 1150. <u>SS</u>	
1	1 PC FRT BUMPER <i>Dehd</i>	1,250.50 ✓	
2	1 PC FRT BUMPER REINFORCEMENT <i>men Dented</i>	356.70 <i>42</i> ✓	
3	1 PC FRT BUMPER GRILLE <i>men</i>	107.20 ✓	
4	2 PCS FRT BUMPER RETAINER <i>men</i>	62.80 31.40 ✓	
5	1 PC FRT GRILLE <i>al</i>	4581.90 395.20 ✓	
6	1 PC FRONT GRILLE TOP CHROME <i>at</i>	3665.52 302.50 ✓	
7	1 PC FRT "H" EMBLEM <i>men</i>	30.60 ✓	
8	1 PC HEADLAMP LH <i>bulbed</i>	2,315.50 ✓	
9	1 PC HEADLAMP LOWER RETAINER LH <i>not a</i>	40.90 ✓	
		4,811.90	
	Less 20%	962.38	3,849.52
	Special Net		
10	1 PC FRT NUMBER PLATE <i>crushed</i>	50.00 ✓	
		50.00	50.00
	Labour		
11	1 TO CHECK WIRING	50.00 <i>30</i>	
12	1 TO SPRAY PAINTING	600.00 <i>350</i>	
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00 <i>400</i>	
		1,250.00	1,250.00

780

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2100285
Date: 02 Nov 2021
Veh Reg No: SLM6345E
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chasis No: GK81102211
Reg. Date: 04/04/2017
Your Ref No: SFG1730L

Claim Type: Third Party
Accident Date: 11/09/2021
TP Veh Reg No: SFG1730L

Estimate Repair Cost to Vehicle No :SLM6345E

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 5,149.52
	Add GST @ 7%		360.47
	Total Amount Payable		S\$ 5,509.99

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED AND NINE AND CENTS
NINETY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
H/S. 03/11/21.

03 Days

total: 4495.52

H/S: 3.6K

3.6K