



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|------------------------|----------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref: | CS3/CTI21011268/Bqy3 |
| 3 ANSON ROAD #16-00 | | Date: | 05/11/2021 |
| SPRINGLEAF TOWERSINGAPORE 079909 | | Code: | CTI |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| Insured Veh. | GBH 9731Z | Veh. Inspected | SLF 8906K |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | SNM21D206296/C02/GBH9731 Z/TANKW | Excess (\$) | 0.00 |
| Assign From | TAN KIAN WEI BILLY | Assign Date | 05/11/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 01/11/2021 | Inspection Date | 05/11/2021 |
| Survey held at | LEE LUEW SING MOTORS NO 10 ANG MO KIO INDUSTRIAL PARK 2A #03-10 AMK AUTOPOINT SINGAPORE 568047 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | |