

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (S) PTE LTD		Ref: CS3/MSG21011273/Btf3	
4 SHENTON WAY #21-01		Date: 05/11/2021	
SGX CENTRE 2 SINGAPORE 068807		Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SMH 5998S	Veh. Inspected	SMY 7013G
Policy No.	29115298QMX	Coverage (\$)	0.00
Claim No.	638696	Excess (\$)	0.00
Assign From	MERIMEN (NOR AZIAN BINTE NOORDIN)	Assign Date	05/11/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/11/2021	Inspection Date	05/11/2021
Survey held at	8 Kaki Bukit Avenue 4, #04-03, Premier@Kaki Bukit		
Repairer	FC GARAGE		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			