

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011283/RPA3Q2**Date:** 02/12/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0005655_01
Claimant Vehicle No :	SBL30B	Insured Vehicle No :	GBE2838L
Date of Loss:	27/10/2021	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBL30B	Engine No:	CZD246356
Make & Model:	VOLKSWAGEN GOLF, 1.4 1.4 TSI R-LINE AT SR (A)	Chassis No:	WVWZZZAUZHW019037
Reg. Date:	18/08/2016 (Man. Year: 2016)	Odometer:	38001 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35 R19	Rear Tyre Size:	225/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,715.70	1,173.50	1,542.20	56.79
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,260.00	740.00	520.00	41.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,986.70	1,924.50	2,062.20	51.73
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,986.70	1,500.00	2,486.70	62.37
+ GST 7.00/7.00% (S\$)	279.07	105.00	174.07	62.38
Nett Amount (S\$)	4,265.77	1,605.00	2,660.77	62.37
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,147.49		

INSPECTION

Date of Assignment:	05/11/2021	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	16/11/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2022)

Parts: 144 VOLKSWAGEN GOLF 1.4 1.4 TSI R-LINE AT SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBL30B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,056.00 FL	*1,056.00 FL
2	2		*REAR PARKING SENSOR CTR LH & RH	Not Necessary	416.00 FL	*- FL
3	1		*REAR NUMBER PLATE	Bent	40.00 FS	*35.00 FS
4	2		*REAR NUMBER PLATE LAMP LH & RH	Not Necessary	162.00 FL	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Not Necessary	395.00 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	2		*REAR BUMPER SIDE RETAINER LH & RH	Not Necessary	96.00 FL	*- FL
8	1		*REAR BUMPER SPONGE	Not Necessary	84.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	555.00 FL	*- FL
10	1		*EMBLEM - GOLF	Necessary	95.00 FL	*95.00 FL
11	1		*EMBLEM - TSI	Necessary	84.00 FL	*84.00 FL
12	1		*TAILGATE - REPAIR (NPA)	Repair	-	*- FL
13	1		*END PANEL - REPAIR (NPA)	Not Necessary	-	*- FL
14	1		*TAILGATE RUBBER - CHECK (NPA)	Not Necessary	-	*- FL
15	1		*TAILGATE LOCK - CHECK (NPA)	Not Necessary	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,013.00	1,300.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	297.30	126.50
Total Parts (\$\$)	2,715.70	1,173.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	New	80.00	0.00
2	TO INSTALL PARKING SENSOR & DIAGNOSE FUNCTION	New	80.00	40.00
3	TO REPAIR ON TAILGATE & END PANEL. TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	New	500.00	300.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,260.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >