

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Nov 2021)

Parts: 144 VOLKSWAGEN GOLF 1.4 1.4 TSI R-LINE AT SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBL30B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                   | %Disc | %Depr | Amount              |
|-----|-----|----------|-----------------------------------------------|-------|-------|---------------------|
| 1   | 1   |          | *REAR BUMPER <i>de/</i>                       | 10.00 | 0.00  | *1,056.00 FL        |
| 2   | 2   |          | *REAR PARKING SENSOR CTR LH & RH <i>? Xan</i> | 10.00 | 0.00  | *416.00 FL X        |
| 3   | 1   |          | *REAR NUMBER PLATE <i>bt</i>                  | 0     | 0.00  | <i>35</i> *49.00 FS |
| 4   | 2   |          | *REAR NUMBER PLATE LAMP LH & RH <i>Xan</i>    | 10.00 | 0.00  | *182.00 FL X        |
| 5   | 1   |          | *REAR BUMPER LOWER GARNISH <i>? Xan</i>       | 10.00 | 0.00  | *395.00 FL X        |
| 6   | 10  |          | *REAR BUMPER CLIPS <i>an</i>                  | 10.00 | 0.00  | *30.00 FL           |
| 7   | 2   |          | *REAR BUMPER SIDE RETAINER LH & RH <i>Xan</i> | 10.00 | 0.00  | *96.00 FL X         |
| 8   | 1   |          | *REAR BUMPER SPONGE <i>? Xan</i>              | 10.00 | 0.00  | *84.00 FL X         |
| 9   | 1   |          | *REAR BUMPER REINFORCEMENT <i>? Xan</i>       | 10.00 | 0.00  | *555.00 FL X        |
| 10  | 1   |          | *EMBLEM - GOLF <i>an</i>                      | 10.00 | 0.00  | *95.00 FL           |
| 11  | 1   |          | *EMBLEM - TSI <i>an</i>                       | 10.00 | 0.00  | *84.00 FL           |
| 12  | 1   |          | *TAILGATE - REPAIR                            | 10.00 | 0.00  | -                   |
| 13  | 1   |          | *END PANEL - REPAIR <i>Xan</i>                | 10.00 | 0.00  | -                   |
| 14  | 1   |          | *TAILGATE RUBBER - CHECK <i>Xan</i>           | 10.00 | 0.00  | -                   |
| 15  | 1   |          | *TAILGATE LOCK - CHECK <i>Xan</i>             | 10.00 | 0.00  | -                   |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                        |                |          |
|----------------------------------------|----------------|----------|
| Sub Total (\$\$)                       | <i>1265</i>    | 3,013.00 |
| - List Item Discount on L Items (\$\$) | <i>10%</i>     | 297.30   |
| Total Parts (\$\$)                     | <i>1138.50</i> | 2,715.70 |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS*S/N - 38*

## Estimates on Miscellaneous Items

Qty Particulars

Amount

## Miscellaneous Items

1 OD/TP Case (Insurer)

11.00

Sub Total (\$)

11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

1 TO INSPECT REAR LIGHTING MECHANISM &amp; CHECK WIRING

New

80.00

2 TO INSTALL PARKING SENSOR &amp; DIAGNOSE FUNCTION

New

80.00

3 TO REPAIR ON TAILGATE &amp; END PANEL. TO REMOVE &amp; REPLACE DAMAGED ITEMS, REALIGN CONNECTION

New

500.00

4 TO SPRAY PAINT ON REPAIRED AREAS

New

600.00

Gross Labour Cost (\$)

1,260.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 900 10028

4 days

4/5

16/11/21 @ 1150

Resurvey after repair

1138.50

35.00

11.00

740.00

1924.50

20%

1539.60

4/5 - 1,500