

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0896/2021/JT
DATE : 2-Nov-21
WIP : 51520

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 Sunday

Johnny Boo

6-Dec-21

OWNER'S NAME : MR DUBEY ADITYA
ADDRESS : 30 KAMPONG EUNOS
#03-03
SINGAPORE 41777
TELEPHONE : HP +65 90179546
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 20701799197
VEHICLE NO : **SMX 1823 E**
MODEL CODE : AUDI Q3 14 TFSI S TRONIC
MODEL YEAR : 29/12/2020
ENGINE NO : CZD C21236
CHASSIS NO : WAUZZZF33M1049810
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Oct-21
PLACE OF ACCIDENT : 92 DUNLOP ST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 1823 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$ 560.00
2	TO REMOVE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS REAR FENDER AND- <i>door hinges - sprayed</i>	\$	3,500.00	\$ 1,750.00
3a	Added labour charges - see attached	\$	1,600.00	\$ 800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 8,492.00	\$ 4,302.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 1823 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR LH	1	\$ 2,805.00	\$	2,244.00
2	FRONT DOOR OUTER DOOR SEAL LH	1	\$ 166.00	\$	132.80
3	FRONT DOOR ATTACHEMENTS PARTS	1	\$ 157.00		
4	FRONT DOOR CATCH	1	\$ 120.00	\$	96.00
5	FRONT DOOR COVER LH	1	\$ 268.00	\$	214.40
6	REAR DOOR LH	1	\$ 2,909.00	\$	2,327.20
7	REAR DOOR OUTER SEAL LH	1	\$ 135.00	\$	108.00
8	REAR DOOR ATTACHMENTS PARTS	1	\$ 311.00		
9	REAR DOOR CATCH	1	\$ 120.00	\$	96.00
10	REAR DOOR INNER SEAL	1	\$ 191.00		
11	SEAL FOR SILL PANEL LH	1	\$ 135.00		
12	REAR DOOR HINGE HALF UPPER PART LH	1	\$ 47.00	\$	37.60
13	REAR DOOR HINGE HALF LOWER PART	1	\$ 44.00	\$	34.48
14	REAR DOOR COVER LH	1	\$ 257.00	\$	205.20
15	REAR WHEEL COVER LH	1	\$ 268.00		
16	SUNDRIES	1	\$ 250.00	\$	22.40
TOTAL SPARE PARTS		:	\$ 8,183.00	\$	5,518.08
TOTAL LABOUR CHARGES		:	\$ 8,492.00	\$	4,302.00
GRAND TOTAL		:	\$ 16,675.00	\$	9,820.08

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT