



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21011294/Bvf3e2	
			Date: 30/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 668T	Veh. Inspected	GBH 2699E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/21/2070	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	05/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 5MT	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y10K210050	Colour	SILVER
	Odometer	172599 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	155 R12	FALKEN	6 mm
	L/H Rear Tyre	155 R12	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/10/2021	Inspection Date	08/11/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	