



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21011295/Atf3n2	
			Date: 17/01/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1308B	Veh. Inspected	SKN 7644S	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/21/2001	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	05/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2120342B003480	Colour	BLACK	
Odometer	147312 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	PIRELLI	6 mm	
L/H Front Tyre	245/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2021	Inspection Date	02/11/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	