



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 3486H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (CONSISTENT)	NOT NECESSARY	838.04	-
1	FRT HEADLAMP (CONSISTENT)	CUT	1,588.72	1,588.72
1	FRT FENDER (CONSISTENT)	BUCKLED	431.68	431.68
1	FRT FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	364.28	-
1	FRT BUMPER (CONSISTENT)	DEFORMED	391.55	391.55
1	FRT BUMPER FOG LAMP GARNISH (CONSISTENT)	CUT	128.73	128.73
1	FRT BUMPER TOW HOOK COVER (CONSISTENT)	NOT NECESSARY	38.72	-
2	FRT BUMPER TOP CHROME MOULDING (CONSISTENT)	NOT NECESSARY	211.40	-
1	FRT BUMPER LOGO (CONSISTENT)	NOT NECESSARY	636.02	-
1	FRT BUMPER GRILLE (CONSISTENT)	NOT NECESSARY	288.27	-
1	FRT BUMPER INNER SPONGE (CONSISTENT)	NOT NECESSARY	104.95	-
1	FRT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	381.77	-
1	FRT BUMPER SIDE RETAINERS (CONSISTENT)	N/S CRACKED	144.66	77.33
1	FRT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	1,039.44	-
1	AIR CON CONDENSER (CONSISTENT)	NOT NECESSARY	1,521.30	-
1	FRT RADIATOR (CONSISTENT)	NOT NECESSARY	1,435.31	-
1	FRT BUMPER FOG LAMP GARNISH (OCEPER) (CONSISTENT)	DEFORMED	73.37	73.37
	LESS 25% DISCOUNT		-2,404.55	-672.85
			7,213.66	2,018.53
	<u>LABOUR</u>			
	TO CHECK WIRING.		100.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REVERSE SENSOR .	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT EXHAUST .	NOT NECESSARY	200.00	-
	PANEL BEATING.		2,000.00	500.00
	SPRAY PAINTING.		2,000.00	400.00
	TO UNDERSEAL.	NOT NECESSARY	250.00	-
			4,820.00	930.00
	GRAND TOTAL		12,033.66	2,948.53

Report Ref No. CC4/ASM21011302/Aps3q2



RECOMMENDED COST OF REPAIRS			2,948.53
-----------------------------	--	--	-----------------

Report Ref No. CC4/ASM21011302/Aps3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.