

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011309/GQY3N2**Date:** 13/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00062942100
Claimant Vehicle No :	SKB986P	Insured Vehicle No :	YN5522H
Date of Loss:	03/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206322/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB986P	Engine No:	65V06943
Make & Model:	PORSCHE BOXSTER, TIPTRONIC (A)	Chassis No:	WPOZZZ98ZVS604129
Reg. Date:	16/05/1997 (Man. Year: 1997)	Odometer:	123567 km
Colour:	White		
Engine Capacity:	2480 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,377.45	4,506.30	4,871.15	51.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,710.00	1,370.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,457.45	6,216.30	6,241.15	50.10
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	12,457.45	4,950.00	7,507.45	60.26
+ GST 7.00/7.00% (S\$)	872.02	346.50	525.52	60.26
Nett Amount (S\$)	13,329.47	5,296.50	8,032.97	60.26

INSPECTION

Date of Assignment:	08/11/2021	
Date Inspected:	05/11/2021	Inspected At: 60 JALAN LAM HUAT, #05-01 CARROS CENTRE REPAIRER: VIN'S MOTOR PTE LTD
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Jun 2022)	
Parts:	N/A	PORSCHE BOXSTER TIPTRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB986P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FENDER	Buckled	3,870.00 FL	*2,350.00 FL
2	1		*REAR LH TAILLAMP	Cracked	780.00 FL	*780.00 FL
3	1		*REAR BUMPER	Torn	1,913.00 FL	*1,752.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,014.00 FL	*- FL
5	1		*REAR BUMPER LH SIDE RETAINER	Deformed	511.00 FL	*125.00 FL
6	2		*REAR BUMPER SENSOR	Not Necessary	820.00 FL	*- FL
7	1		*REAR BUMPER LH INNER HEATER SHIELD	Not Necessary	375.00 FL	*- FL
8	1		*REAR BUMPER CENTRE INNER HEATER SHIELD	Not Necessary	588.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,871.00	5,007.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	493.55	500.70
Total Parts (\$\$)	9,377.45	4,506.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX SEAT CUSHION AND ROOF LINING	New	280.00	160.00
2	TO REMOVE AND REFIX SOFT TOP	New	500.00	250.00
3	TO REPAIR DAMAGES	New	1,100.00	800.00
4	TO SPRAY PAINTING	New	1,200.00	500.00
Gross Labour Cost (\$\$)			3,080.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >