

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 08 Nov 2021

Preliminary Advice

Insured Vehicle No	: YN5522H	Accident Date	: 03/11/2021
TP Vehicle No	: SKB986P	Assignment Date	: 08/11/2021
Make	: PORSCHE BOXSTER	Est. Duration of Repair	: 6
Date of Inspection	: 05/11/2021		
Inspection At	: VINS AUTOMOTIVE GROUP (HQ) 160 SIN MING DRIVE #03-03 SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,080.00 (LABOUR ONLY)
Revised Amount	:S\$	1,710.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,710.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending for parts prices.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.